



DPX™ AUXILIARY INPUT CONVERTER

APPLICATION GUIDE

PIE Auxiliary Input Converters allow you to convert the CD changer, Satellite radio or RSE port of your OEM radio into auxiliary input. Auxiliary devices such as Mobile Video Systems, MP3 and Digital Satellite Radio can be added to the OEM radio WITHOUT FM MODULATION, resulting in optimum sound quality.

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION	NOTES
<u>ACURA</u>				
3.2 TL	2004-2007	HON03/PC-SON	14-Pin connector at headunit	Not compatible if equipped with factory XM or external CD Changer.
CL	1997-1999	HON-AUX	8-Pin DIN connector in trunk	Not compatible if equipped with external CD Changer.
Integra	1992-2001	HON-AUX	8-Pin DIN connector in trunk	Not compatible if equipped with external CD Changer.
Legend	1992-1995	HON-AUX	8-Pin DIN connector in trunk	Not compatible if equipped with external CD Changer.
MDX	2005-2006	HON03/PC-SON	14-Pin connector at headunit	Not compatible if equipped with factory XM or external CD Changer.
RL	1996-2001	HON-AUX	8-Pin DIN connector in trunk	Not compatible if equipped with factory Navigation or external CD Changer.
TL	1995-1998	HON-AUX	8-Pin DIN connector in trunk	Not compatible if equipped with external CD Changer.
TSX	2004-2007	HON03/PC-SON	14-Pin connector at headunit	Not compatible if equipped with factory XM radio.
Vigor	1992-1994	HON-AUX	8-Pin DIN connector in trunk	Not compatible if equipped with external CD Changer.

Note: HON03/PC-SON also requires PIE part # HON03-F/MM if vehicle is equipped with Navigation.

<u>AUDI</u>				
A3	2006-2007	VWR-AUX*	8-Pin connector at headunit	Use Part # AUD-AUX if pre-wired with a 13-Pin DIN connector.
A4	1998-2006	VWR-AUX	8-Pin connector at headunit	Use Part # AUD-AUX if pre-wired with a 13-Pin DIN connector.
A4	2007	VW02-AUX	8-Pin connector at headunit	Use Part # AUD-AUX if pre-wired with a 13-Pin DIN connector.
A8	1998-2005	VWR-AUX	8-Pin connector at headunit	Use Part # AUD-AUX if pre-wired with a 13-Pin DIN connector.
Allroad	2001-2005	VWR-AUX	8-Pin connector at headunit	Use Part # AUD-AUX if pre-wired with a 13-Pin DIN connector.
Cabriolet	1998	VWR-AUX	8-Pin connector at headunit	Use Part # AUD-AUX if pre-wired with a 13-Pin DIN connector.
RS6	2003	VWR-AUX	8-Pin connector at headunit	Use Part # AUD-AUX if pre-wired with a 13-Pin DIN connector.
S4	2000-2005	VWR-AUX	8-Pin connector at headunit	Use Part # AUD-AUX if pre-wired with a 13-Pin DIN connector.
S6	2002-2003	VWR-AUX	8-Pin connector at headunit	Use Part # AUD-AUX if pre-wired with a 13-Pin DIN connector.
S8	2001-2003	VWR-AUX	8-Pin connector at headunit	Use Part # AUD-AUX if pre-wired with a 13-Pin DIN connector.
TT	2000-2005	VWR-AUX	8-Pin connector at headunit	Use Part # AUD-AUX if pre-wired with a 13-Pin DIN connector.
A6/ A8/ Q7	2006-UP	Not Compatible		

*Note : Requires PIE Part # AA3-HAR if not pre-wired.

Note 1: Not compatible if equipped with a factory External CD Changer or Satellite.

Note 2: 2001 and up models equipped with the "Symphony II" (6-disc in-dash) headunit or radios using 20-pin one piece connector will also require PIE Part # AA3-HAR.

Note 3: Not compatible if vehicle is equipped with factory Navigation, Satellite, or external CD changer.

<u>BMW</u>				
3-Series	1996-2006	BMW/PC-SON	3 & 6-Pin connectors in rear driver side.	Not compatible with models equipped with DSP.
5-Series	1997-2003	BMW/PC-SON	3 & 6-Pin connectors in rear driver side.	Not compatible with models equipped with DSP.
5-Series	2004-UP	Not Compatible		
6-Series	2004-UP	Not Compatible		
7-Series	1996 - Up	Not Compatible		
8-Series	1996-1997	BMW/PC-SON	3 & 6-Pin connectors in rear driver side.	Not compatible with models equipped with DSP.
M	2000-2002	BMW/PC-SON	3 & 6-Pin connectors in rear driver side.	Not compatible with models equipped with DSP.
M3	1996-2003	BMW/PC-SON	3 & 6-Pin connectors in rear driver side.	Not compatible with models equipped with DSP.
M5	2000-2003	BMW/PC-SON	3 & 6-Pin connectors in rear driver side.	Not compatible with models equipped with DSP.
X3	2004-2006	BMW/PC-SON	3 & 6-Pin connectors in rear driver side.	Not compatible with models equipped with DSP.
X5	2001-2006	BMW/PC-SON	3 & 6-Pin connectors in rear driver side.	Not compatible with models equipped with DSP.
Z3	1996-2002	BMW/PC-SON	3 & 6-Pin connectors in rear driver side.	Not compatible with models equipped with DSP.
Z4	2003-2006	BMW/PC-SON	3 & 6-Pin connectors in rear driver side.	Not compatible with models equipped with DSP.
Z8	2000-2003	BMW/PC-SON	3 & 6-Pin connectors in rear driver side.	Not compatible with models equipped with DSP.



DPX™ AUXILIARY INPUT CONVERTER APPLICATION GUIDE

PIE Auxiliary Input Converters allow you to convert the CD changer, Satellite radio or RSE port of your OEM radio into auxiliary input. Auxiliary devices such as Mobile Video Systems, MP3 and Digital Satellite Radio can be added to the OEM radio WITHOUT FM MODULATION, resulting in optimum sound quality.

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION	NOTES
------------	---------	-----------	----------	-------

Note 1: Not compatible with I-Drive.

Note 2: Not compatible with factory satellite installed.

BUICK

		PIE Part #	Without XM	With XM	
Allure	2005-2007	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Allure	2005-2007	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Century	2004-2005	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Century	2004-2005	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Enclave	2007-2008	GM12LAN-AUX/S	GMLAN-R1	GMLAN-X1	Must have 'CAT' button.
LaCrosse	2005-2007	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
LaCrosse	2005-2007	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Lucerne	2006-2007	GM12LAN-AUX/S	GMLAN-R1	GMLAN-X1	Must have 'CAT' button.
Rainier	2004-2007	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Rainier	2004-2007	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Rendezvous	2002-2007	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Rendezvous	2003-2007	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.

Note 1: GM12LAN-AUX/S requires separate harness - Is compatible with factory XM installed, and navigation radios.

Note 2: GM12-AUXv2 is compatible with factory XM installed and navigation radios.

CADILLAC

		PIE Part #	Without XM	With XM	
Catera *	1997-1999	GM10-AUX	N/A	N/A	Not compatible with 2000-Up Catera
DTS	2007-2008	GM12LAN-AUX/S	N/A	GMLAN-X1	Must have factory XM Satellite installed.
Escalade	1999-2002	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD changer.
Escalade	2003-2006	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Escalade	2003-2006	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Escalade	2007-2008	GM12LAN-AUX/S	GMLAN-R1	GMLAN-X1	Must have 'CAT' button.
SRX	2004-2006	GM12LAN-AUX/S	N/A	GM12-X2	Must have factory XM Satellite installed.
SRX	2007-2008	GM12LAN-AUX/S	GMLAN-R1	GMLAN-X1	Must have 'CAT' button.

*Note 1: Catera requires Cadillac factory CD data cable Part # 12484910 if not pre-wired.

Note 2: GM9-AUX not compatible with single DIN 6-disc (in-dash) slave CD Changer; GM9-AUX takes the place of this 6-disc slave CD Changer.

Note 3: GM radios 2000 and earlier are not capable of controlling two units; therefore, these radios will need to have the slave unit disconnected.

Note 4: GM12LAN-AUX/S requires separate harness - Is compatible with factory XM installed, and navigation radios.

Note 5: GM12-AUXv2 is compatible with factory XM installed and navigation radios.

CHEVROLET

		PIE Part #	Without XM	With XM	
Astro Van	1996-2005	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD changer.
Avalanche	2002	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD changer.
Avalanche	2003-2006	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Avalanche	2003-2006	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Avalanche	2007-2008	GM12LAN-AUX/S	GMLAN-R1	GMLAN-X1	Must have 'CAT' button.
Aveo	2004-2005	Not Compatible			
Blazer	1998-2002	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD changer.
Blazer	2003-2005	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Blazer	2003-2005	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
*Camaro	1997-2002	GM9-AUX	N/A	N/A	AM/FM/CASS radios only.
Cavalier	1996-1999	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD changer.



DPX™ AUXILIARY INPUT CONVERTER

APPLICATION GUIDE

PIE Auxiliary Input Converters allow you to convert the CD changer, Satellite radio or RSE port of your OEM radio into auxiliary input. Auxiliary devices such as Mobile Video Systems, MP3 and Digital Satellite Radio can be added to the OEM radio WITHOUT FM MODULATION, resulting in optimum sound quality.

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION		NOTES
			PIE Part #	Without XM	
Cavalier	2003-2005	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Cavalier	2003-2005	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Cobalt	2005-2007	Not Compatible			
Colorado	2004-2008	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Colorado	2004-2008	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Corvette	1997-2004	GM10-AUX	N/A	N/A	Use with PIE part # COR-HAR if not pre-wired.
Corvette	2005-2008	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Corvette	2005-2008	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Express Van	2003-2005	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Express Van	2003-2005	GM12LAN-AUX/S	N/A	GM12-X2	Must have factory XM Satellite installed.
HHR	2006-2007	Not Compatible			
Equinox	2005-2007	Not Compatible			
Impala	1995-1997	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD changer.
Impala	2002-2005	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Impala	2003-2005	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Impala	2006-2008	GM12LAN-AUX/S	GMLAN-R1	GMLAN-X1	Must have 'CAT' button.
Lumina	1996-1999	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD changer.
Lumina	2003-2006	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Lumina	2003-2006	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Malibu/Max	1997-2000	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD changer.
Malibu/Max	2002-2003	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Malibu/Max	2004-2008	Not Compatible			
Monte Carlo	1996-1999	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD changer.
Monte Carlo	2003-2005	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Monte Carlo	2003-2005	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Monte Carlo	2006-2007	GM12LAN-AUX/S	GMLAN-R1	GMLAN-X1	Must have 'CAT' button.
C/K Truck	1995-2002	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD changer.
C/K Truck	2003-2006	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
C/K Truck	2003-2006	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Silverado	1995-2002	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD changer.
Silverado	2003-2006	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Silverado	2003-2006	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Silverado Classic	2007	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Silverado Classic	2007	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Silverado New Body	2007-2008	GM12LAN-AUX/S	GMLAN-R1	GMLAN-X1	Must have 'CAT' button.
SSR	2003-2006	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
SSR	2003-2006	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Suburban	1995-2002	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD changer.
Suburban	2003-2006	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Suburban	2003-2006	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Suburban	2007-2008	GM12LAN-AUX/S	GMLAN-R1	GMLAN-X1	Must have 'CAT' button.
Tahoe	1995-2002	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD changer.
Tahoe	2003-2006	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Tahoe	2003-2006	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Tahoe	2007-2008	GM12LAN-AUX/S	GMLAN-R1	GMLAN-X1	Must have 'CAT' button.
Trailblazer	2002-2008	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Uplander	2005-2007	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Uplander	2005-2007	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.



DPX™ AUXILIARY INPUT CONVERTER APPLICATION GUIDE

PIE Auxiliary Input Converters allow you to convert the CD changer, Satellite radio or RSE port of your OEM radio into auxiliary input. Auxiliary devices such as Mobile Video Systems, MP3 and Digital Satellite Radio can be added to the OEM radio WITHOUT FM MODULATION, resulting in optimum sound quality.

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION		NOTES
Venture	1997-1999	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD changer.
Venture	2002-2005	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Venture	2004-2005	GM12LAN-AUX/S	N/A	GM12-X2	Must have factory XM Satellite installed.

Note 1: GM9-AUX not compatible with 1995 -1999 AM/FM/CD radios.

Note 2: GM9-AUX not compatible with single DIN 6-disc (in-dash) slave CD Changer; GM9-AUX takes the place of this 6-disc slave CD Changer.

Note 3: GM radios 2000 and earlier are not capable of controlling two units; therefore, these radios will need to have the slave unit disconnected.

*Note 4: Camaro radio must be AM/FM/CASS radio.

Note 5: GM12LAN-AUX/S requires separate harness - Is compatible with factory XM installed, and navigation radios.

Note 6: GM12-AUXv2 is compatible with factory XM installed and navigation radios.

CHRYSLER

300	2005-2007	CHRY04-AUX/S	10 & 22-Pin connectors at headunit		Compatible with REF, RAQ, RAK, REC radios only.
300	2005-2007	CHRY04-AUX	10 & 22-Pin connectors at headunit		Compatible with RAQ, RAK, REC radios only.
300M	1999-2001	CHRY98-AUX	8-Pin connector at headunit		Not compatible if equipped with factory external CD Changer.
300M	2002-2004	CHRY02-AUX	10-Pin connector at headunit		Not compatible with "RBQ", "RB4", "RAH", "REV" and "RBK" radios.
Aspen	2007	CHRY04-AUX/S	10 & 22-Pin connectors at headunit		Compatible with REF, RAQ, RAK, REC radios only.
Aspen	2007	CHRY04-AUX	10 & 22-Pin connectors at headunit		Compatible with RAQ, RAK, REC radios only.
Concorde	1998-2001	CHRY98-AUX	8-Pin connector at headunit		Not compatible if equipped with factory external CD Changer.
Concorde	2002-2005	CHRY02-AUX	10-Pin connector at headunit		Not compatible with "RBQ", "RB4", "RAH", "REV" and "RBK" radios.
Crossfire	2004-2006	Not Compatible			
Grand Voyager	2000	CHRY-AUX	8-Pin DIN connector at headunit		Not compatible if equipped with factory external CD Changer.
LeBaron	1995	CHRY-AUX	8-Pin DIN connector at headunit		Not compatible if equipped with factory external CD Changer.
LHS	1995-1998	CHRY-AUX	8-Pin DIN connector at headunit		Not compatible if equipped with factory external CD Changer.
LHS	1999-2001	CHRY98-AUX	8-Pin connector at headunit		Not compatible if equipped with factory external CD Changer.
LHS	2002-2004	CHRY02-AUX	10-Pin connector at headunit		Not compatible with "RBQ", "RB4", "RAH", "REV" and "RBK" radios.
New Yorker	1995-1996	CHRY-AUX	8-Pin DIN connector at headunit		Not compatible if equipped with factory external CD Changer.
Pacifica	2003-2008	CHRY02-AUX	10-Pin connector at headunit		Not compatible with "RBQ", "RB4", "RAH", "REV" and "RBK" radios.
PT Cruiser	2001	CHRY98-AUX	8-Pin connector at headunit		Not compatible if equipped with factory external CD Changer.
PT Cruiser	2002-2005	CHRY02-AUX	10-Pin connector at headunit		Not compatible with "RBQ", "RB4", "RAH", "REV" and "RBK" radios.
PT Cruiser	2006-2008	CHRY04-AUX/S	10 & 22-Pin connectors at headunit		Compatible with REF, RAQ, RAK, REC radios only.
PT Cruiser	2006-2008	CHRY04-AUX	10 & 22-Pin connectors at headunit		Compatible with RAQ, RAK, REC radios only.
Sebring	1995-2000	CHRY-AUX	8-Pin DIN connector at headunit		Not compatible if equipped with factory external CD Changer.
Sebring	2001	CHRY98-AUX	8-Pin connector at headunit		Not compatible if equipped with factory external CD Changer.
Sebring	2002-2006	CHRY02-AUX	10-Pin connector at headunit		Not compatible with "RBQ", "RB4", "RAH", "REV" and "RBK" radios.
Town & Country	1995-2000	CHRY-AUX	8-Pin DIN connector at headunit		Not compatible if equipped with factory external CD Changer.
Town & Country	2001	CHRY98-AUX	8-Pin connector at headunit		Not compatible if equipped with factory external CD Changer.
Town & Country	2002-2007	CHRY02-AUX	10-Pin connector at headunit		Not compatible with "RBQ", "RB4", "RAH", "REV" and "RBK" radios.
Voyager	2000	CHRY-AUX	8-Pin DIN connector at headunit		Not compatible if equipped with factory external CD Changer.
Voyager	2001	CHRY98-AUX	8-Pin connector at headunit		Not compatible if equipped with factory external CD Changer.
Voyager	2002-2004	CHRY02-AUX	10-Pin connector at headunit		Not compatible with "RBQ", "RB4", "RAH", "REV" and "RBK" radios.

Note 1: CHRY98-AUX - must be 'Rounded Face' radio with 'CD-C' button.

Note 2: CHRY02-AUX not compatible if equipped with factory Satellite radio or external CD Changer (use PIE Part #'s X3 & X3-CHRY02 instead).

Note 3: CHRY02-AUX - not compatible with "RBQ" (6-disc in-dash), "RB4" (Navigation), "RAH", "REV" and "RBK" radios.



DPX™ AUXILIARY INPUT CONVERTER

APPLICATION GUIDE

PIE Auxiliary Input Converters allow you to convert the CD changer, Satellite radio or RSE port of your OEM radio into auxiliary input. Auxiliary devices such as Mobile Video Systems, MP3 and Digital Satellite Radio can be added to the OEM radio WITHOUT FM MODULATION, resulting in optimum sound quality.

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION	NOTES
Note 4: CHRY-AUX - radio must be one of the following CD Changer controller headunits: <ul style="list-style-type: none"> • 5-preset radio with 5-band EQ, "DISC ^" and "DISC v" on presets 1 and 5, and "MODE" button, • 6-preset radio with Bass and Treble slider controls, "DIRECT DISC SELECT 1-6" printed above radio presets, and "MODE/EJECT" button. 				
Note 5: CHRY04-AUX/S not compatible if equipped with factory Satellite radio. Is compatible with factory VES installed.				
Note 6: CHRY04-AUX not compatible if equipped with factory VES. Is compatible with factory Satellite radio installed.				
<u>DODGE</u>				
Avenger	1995-2000	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Caliber	2007-2008	CHRY04-AUX/S	10 & 22-Pin connectors at headunit	Compatible with REF, RAQ, RAK, REC radios only.
Caliber	2007-2008	CHRY04-AUX	10 & 22-Pin connectors at headunit	Compatible with RAQ, RAK, REC radios only.
Caravan	1995-2000	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Caravan	2001	CHRY98-AUX	8-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
Caravan	2002-2007	CHRY02-AUX	10-Pin connector at headunit	Not compatible with "RBQ", "RB4", "RAH", "REV" and "RBK" radios.
Charger	2006-2007	CHRY04-AUX/S	10 & 22-Pin connectors at headunit	Compatible with REF, RAQ, RAK, REC radios only.
Charger	2006-2007	CHRY04-AUX	10 & 22-Pin connectors at headunit	Compatible with RAQ, RAK, REC radios only.
Dakota	1995-2000	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Dakota	2001	CHRY98-AUX	8-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
Dakota	2002-2004	CHRY02-AUX	10-Pin connector at headunit	Not compatible with "RBQ", "RB4", "RAH", "REV" and "RBK" radios.
Dakota	2005-2008	CHRY04-AUX/S	10 & 22-Pin connectors at headunit	Compatible with REF, RAQ, RAK, REC radios only.
Dakota	2005-2008	CHRY04-AUX	10 & 22-Pin connectors at headunit	Compatible with RAQ, RAK, REC radios only.
Durango	1998-2000	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Durango	2001	CHRY98-AUX	8-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
Durango	2002-2003	CHRY02-AUX	10-Pin connector at headunit	Not compatible with "RBQ", "RB4", "RAH", "REV" and "RBK" radios.
Durango	2004-2007	CHRY04-AUX/S	10 & 22-Pin connectors at headunit	Compatible with REF, RAQ, RAK, REC radios only.
Durango	2004-2007	CHRY04-AUX	10 & 22-Pin connectors at headunit	Compatible with RAQ, RAK, REC radios only.
Grand Caravan	1995-2000	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Intrepid	1995-2000	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Intrepid	2001	CHRY98-AUX	8-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
Intrepid	2002-2004	CHRY02-AUX	10-Pin connector at headunit	Not compatible with "RBQ", "RB4", "RAH" and "REV" radios.
Magnum	2005-2007	CHRY04-AUX/S	10 & 22-Pin connectors at headunit	Compatible with REF, RAQ, RAK, REC radios only.
Magnum	2005-2007	CHRY04-AUX	10 & 22-Pin connectors at headunit	Compatible with RAQ, RAK, REC radios only.
Neon	1995-2000	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Neon	2001	CHRY98-AUX	8-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
Neon	2002-2005	CHRY02-AUX	10-Pin connector at headunit	Not compatible with "RBQ", "RB4", "RAH", "REV" and "RBK" radios.
Pickup	1995-2000	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Ram	1995-2000	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Ram	2001	CHRY98-AUX	8-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
Ram	2002-2005	CHRY02-AUX	10-Pin connector at headunit	Not compatible with "RBQ", "RB4", "RAH", "REV" and "RBK" radios.
Ram	2006-2008	CHRY04-AUX/S	10 & 22-Pin connectors at headunit	Compatible with REF, RAQ, RAK, REC radios only.
Ram	2006-2008	CHRY04-AUX	10 & 22-Pin connectors at headunit	Compatible with RAQ, RAK, REC radios only.
Spirit	1995	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Stealth	1995-1996	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Stratus	1995-2000	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Stratus	2001	CHRY98-AUX	8-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
Stratus	2002-2006	CHRY02-AUX	10-Pin connector at headunit	Not compatible with "RBQ", "RB4", "RAH", "REV" and "RBK" radios.
Viper	1995-2000	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.



DPX™ AUXILIARY INPUT CONVERTER APPLICATION GUIDE

PIE Auxiliary Input Converters allow you to convert the CD changer, Satellite radio or RSE port of your OEM radio into auxiliary input. Auxiliary devices such as Mobile Video Systems, MP3 and Digital Satellite Radio can be added to the OEM radio WITHOUT FM MODULATION, resulting in optimum sound quality.

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION	NOTES
<p>Note 1: CHRY98-AUX - must be 'Rounded Face' radio with 'CD-C' button.</p> <p>Note 2: CHRY02-AUX not compatible if equipped with factory Satellite radio or external CD Changer (use PIE Part #'s X3 & X3-CHRY02 instead).</p> <p>Note 3: CHRY02-AUX - not compatible with "RBQ" (6-disc in-dash), "RB4" (Navigation), "RAH", "REV" and "RBK" radios.</p> <p>Note 4: CHRY-AUX - radio must be one of the following CD Changer controller headunits:</p> <ul style="list-style-type: none"> • 5-preset radio with 5-band EQ, "DISC ^" and "DISC v" on presets 1 and 5, and "MODE" button, • 6-preset radio with Bass and Treble slider controls, "DIRECT DISC SELECT 1-6" printed above radio presets, and "MODE/EJECT" button. <p>Note 5: CHRY04-AUX/S not compatible if equipped with factory Satellite radio. Is compatible with factory VES installed.</p> <p>Note 6: CHRY04-AUX not compatible if equipped with factory VES. Is compatible with factory Satellite radio installed.</p>				
<u>EAGLE</u>				
Summit	1995-1996	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Talon	1995-1998	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Vision	1995-1997	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
<p>Note: Radio must be one of the following CD Changer controller headunits:</p> <ul style="list-style-type: none"> • 5-preset radio with 5-band EQ, "DISC ^" and "DISC v" on presets 1 and 5, and "MODE" button • 6-preset radio with Bass and Treble slider controls, "DIRECT DISC SELECT 1-6", printed above radio presets, and "MODE/EJECT" button. 				
<u>FORD</u>				
Crown Victoria	1995-1997	FRDF-AUX	16-Pin connector at headunit	Premium Audio System.
Crown Victoria	1995-1997	FRDR-AUX	13 & 14-Pin connectors at RCU in trunk	JBL or LUX Audio System.
Crown Victoria	1998-2002	FRDN-AUX	20-Pin connector at headunit	Use FRDW-AUX if pre-wired.
Crown Victoria	2003-2004	FRD03-AUX	16 & 24-Pin connectors at headunit	Use FRDW-AUX if pre-wired.
Crown Victoria	2005-2006	FRD03-AUX/S	16 & 24-Pin connectors at headunit	Radio must have "SAT" button.
Econoline	1997	FRDF-AUX	16-Pin connector at headunit	Radio must be CD Changer capable.
Econoline	1998-2005	FRDN-AUX	20-Pin connector at headunit	Radio must be CD Changer capable.
Econoline	2006-2008	FRDN-AUX/S	16 & 20-Pin connectors at headunit	Non-navigation radio - radio must have "SAT" button.
Edge	2007-2010	FRD04-AUX	16-Pin connector at headunit	Radio must have "AUX" button.
Escape	2001-2007	FRDN-AUX	20-Pin connector at headunit	Not compatible with 5L8T-18C815-EC radio model.
Escape	2004-2007	FRD03-AUX	16 & 24-Pin connectors at headunit	Radio Model 3L8T-18C815-FB only.
Escape	2004-2007	FRDN-AUX/S	16 & 20-Pin connectors at headunit	Radio must have "SAT" button.
Escape	2004-2007	FRD03-AUX/S	16 & 24-Pin connectors at headunit	Radio must have "SAT" button.
Escape Hybrid	2006-2007	FRDN-AUX/S	16 & 20-Pin connectors at headunit	Radio must have "SAT" button.
Escape Hybrid	2006-2007	FRD03-AUX/S	16 & 24-Pin connectors at headunit	Non-navigation radio - radio must have "SAT" button.
Escape Hybrid	2006-2007	FRDC-AUX	12-Pin connector at headunit	Navigation radio only (takes place of OEM changer).
Escape Hybrid	2006-2007	FRDW-AUX	12-Pin connector under passenger seat	Navigation radio only (takes place of OEM changer).
Escort	1997-2003	FRDW-AUX	12-Pin connector in trunk or rear	Oval-Faced radio-use FRDF-AUX at headunit-if not pre-wired.
Excursion	2000-2005	FRDN-AUX	20-Pin connector at headunit	Radio must be CD Changer capable.
Expedition	1997-1998	FRDF-AUX	16-Pin connector at headunit	Radio must be CD Changer capable.
Expedition	1999-2002	FRDN-AUX	20-Pin connector at headunit	Radio must be CD Changer capable.
Expedition*	2003	FRDN-AUX100	20-Pin connector at headunit	Not compatible if vehicle has factory DVD (RSE).
Expedition*	2004-2006	FRD03-AUX100	16 & 24-Pin connectors at headunit	Not compatible if vehicle has factory DVD (RSE).
Expedition*	2004-2006	FRD03-AUX/S	16 & 24-Pin connectors at headunit	Radio must have "SAT" button & no factory DVD (RSE).
Expedition	2007-2009	FRD04-AUX	16-Pin connector at headunit	Radio must have "AUX" button.
Explorer	1995-1997	FRDF-AUX	16-Pin connector at headunit	Premium Audio System.
Explorer	1995-1997	FRDR-AUX	13 & 14-Pin connectors at RCU in rear passenger side panel	JBL or LUX Audio System.
Explorer	1998-2004	FRDN-AUX	20-Pin connector at headunit	Radio must be CD Changer capable.
Explorer	2004-2005	FRDN-AUX/S	16 & 20-Pin connectors at headunit	Radio must have "SAT" button & no factory DVD (RSE).



DPX™ AUXILIARY INPUT CONVERTER APPLICATION GUIDE

PIE Auxiliary Input Converters allow you to convert the CD changer, Satellite radio or RSE port of your OEM radio into auxiliary input. Auxiliary devices such as Mobile Video Systems, MP3 and Digital Satellite Radio can be added to the OEM radio WITHOUT FM MODULATION, resulting in optimum sound quality.

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION	NOTES
Explorer	2004-2005	FRD03-AUX/S	16 & 24-Pin connectors at headunit	Radio must have "SAT" button & no factory DVD (RSE).
Explorer	2006-2009	FRD04-AUX	16-Pin connector at headunit	Radio must have "AUX" button.
Five hundred	2005-2007	Not Compatible		
F-150 Pick Up	1997	FRDF-AUX	16-Pin connector at headunit	Radio must be CD Changer capable.
F-Series Pick Up	1998-2003	FRDN-AUX	20-Pin connector at headunit	Radio must be CD Changer capable.
F150	2004-2008	FRD04-AUX	16-Pin connector at headunit	Radio must have "AUX" button.
F250	2005-2009	FRD04-AUX	16-Pin connector at headunit	Radio must have "AUX" button.
F350	2005-2009	FRD04-AUX	16-Pin connector at headunit	Radio must have "AUX" button.
F550	2005-2009	FRD04-AUX	16-Pin connector at headunit	Radio must have "AUX" button.
Focus	2000-2003	FRDC-AUX	12-Pin connector at headunit	Not compatible with Blaupunkt Audio system.
Focus	2005-2007	FRD04-AUX	16-Pin connector at headunit	Radio must have "AUX" button.
Freestar	2004-2005	FRD03-AUX	16 & 24-Pin connectors at headunit	Radio models 3F2T-18C868-AJ or 3F2T-18C869-AJ.
Freestar	2004-2005	FRD03-AUX100	16 & 24-Pin connectors at headunit	Radio models 5F2T-18C815-AA or 5F2T-18C868-AA.
Freestyle	2005-2007	FRD04-AUX	16-Pin connector at headunit	Radio must have "AUX" button.
Fusion	2006-2009	FRD04-AUX	16-Pin connector at headunit	Radio must have "AUX" button.
HN80 HeavyDuty	1996-1997	FRDF-AUX	16-Pin connector at headunit	Radio must be CD Changer capable.
Mustang	2001-2004	FRDN-AUX	20-Pin connector at headunit	Radio must be CD Changer capable.
Mustang	2004	FRD03-AUX	16 & 24-Pin connectors at headunit	Radio must be CD Changer capable.
Mustang	2004	FRD03-AUX/S	16 & 24-Pin connectors at headunit	Radio must have "SAT" button.
Mustang	2005-2009	FRD04-AUX	16-Pin connector at headunit	Radio must have "AUX" button.
Ranger	1995-1997	FRDF-AUX	16-Pin connector at headunit	Radio must be CD Changer capable.
Ranger	1998-2004	FRDN-AUX	20-Pin connector at headunit	Radio must be CD Changer capable.
Sport Trac	2000-2005	FRDN-AUX	20-Pin connector at headunit	Radio must be CD Changer capable.
Sport Trac	2004-2005	FRDN-AUX/S	16 & 20-Pin connectors at headunit	Radio must have "SAT" button.
Sport Trac	2004-2005	FRD03-AUX/S	16 & 24-Pin connectors at headunit	Radio must have "SAT" button.
Sport Trac	2007-2009	FRD04-AUX	16-Pin connector at headunit	Radio must have "AUX" button.
Taurus	1996-2006	FRDR-AUX	13 & 14-Pin connectors at RCU in trunk	Oval-Faced radio.
Thunderbird	2001-2003	FRDN-AUX	20-Pin connector at headunit	Radio must be CD Changer capable.
Thunderbird	2004-2005	FRD03-AUX/S	16 & 24-Pin connectors at headunit	Radio must have "SAT" button.
Windstar	1999-2003	FRDN-AUX	20-Pin connector at headunit	Radio must be CD Changer capable.

Note 1: Not compatible with 2003 and up 6-disc headunits not equipped with external CD Changer capabilities.

Note 2: FRD04-AUX not compatible with factory navigation radios. Not compatible if equipped with factory Satellite radio or RSE (Rear Seat Entertainment) Not compatible with Ford Sync System.

*Note 3: 2003-2006 Expedition with Navigation radio will use FRDW-AUX (if pre-wired) or FRDC-AUX.

Note 4: 2004 Models equipped with 6-Disc in-Dash, "THX Certified" Navigation radio may use Part # FRD03-AUX

Note 5: FRD03-AUX/S is not compatible with factory satellite or RSE (Rear Seat Entertainment) installed.

Note 6: FRD03-AUX/S is compatible with touch screen navigation radios, is not compatible with non-touch screen navigation radios.

GMC		PIE Part #	Without XM	With XM	
Acadia	2007-2008	GM12LAN-AUX/S	GMLAN-R1	GMLAN-X1	Must have 'CAT' button.
Canyon	2004-2008	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Canyon	2004-2008	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Jimmy	1998-2002	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD changer.
Envoy	1999-2001	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD changer.
Envoy	2002-2008	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Safari	1996-2005	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD changer.
Sierra	1995-2002	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD changer.



DPX™ AUXILIARY INPUT CONVERTER APPLICATION GUIDE

PIE Auxiliary Input Converters allow you to convert the CD changer, Satellite radio or RSE port of your OEM radio into auxiliary input. Auxiliary devices such as Mobile Video Systems, MP3 and Digital Satellite Radio can be added to the OEM radio WITHOUT FM MODULATION, resulting in optimum sound quality.

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION		NOTES
			Without XM	With XM	
		PIE Part #			
Sierra	2003-2006	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Sierra	2003-2006	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Sierra Classic	2007	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Sierra Classic	2007	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Sierra New Body	2007-2008	GM12LAN-AUX/S	GMLAN-R1	GMLAN-X1	Must have 'CAT' button.
Sonoma	1998-2002	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD changer.
Sonoma	2003-2004	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Sonoma	2003-2004	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Yukon	1995-2002	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD changer.
Yukon / Denali / XL	2003-2006	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Yukon / Denali / XL	2003-2006	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Yukon / Denali / XL	2007-2008	GM12LAN-AUX/S	GMLAN-R1	GMLAN-X1	Must have 'CAT' button.

Note 1: GM9-AUX not compatible with 1995 -1999 AM/FM/CD radios.

Note 2: GM9-AUX not compatible with vehicles equipped with in-dash 6-disc slave units.

Note 3: GM radios 2000 and earlier are not capable of controlling two units; therefore, these radios will need to have the slave unit disconnected.

Note 4: GM12LAN-AUX/S requires separate harness - Is compatible with factory XM installed, and navigation radios.

Note 5: GM12-AUXv2 is compatible with factory XM installed and navigation radios.

HONDA

Accord	1992-1997	HON-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Accord	1998-2002	HON98-AUX	14-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
Accord	2003-2007	HON03/PC-SON	14-Pin connector at headunit	Compatibility includes Hybrid models. Not compatible if factory XM is present.
Civic	1992-1998	HON-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Civic	1999-2005	HON98-AUX	14-Pin connector at headunit	Compatibility includes Si and Hybrid models.
Civic	2006	Not Compatible		
CRV	1997-1998	HON-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
CRV	1999-2004	HON98-AUX	14-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
CRV	2005-2006	HON03/PC-SON	14-Pin connector at headunit	Not compatible if factory XM is present.
Del Sol	1993-1997	HON-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Element	2003-2007	HON03/PC-SON	14-Pin connector at headunit	Not compatible if factory XM is present.
Odyssey	1995-1998	HON-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Odyssey	1999-2004	HON98-AUX	14-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
Odyssey	2005-2007	HON03/PC-SON	14-Pin connector at headunit	Not compatible if factory XM is present.
Pilot	2003-2005	HON98-AUX	14-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
Pilot	2006-2007	HON03/PC-SON	14-Pin connector at headunit	Not compatible if factory XM is present.
Prelude	1992-1998	HON-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Prelude	1999-2001	HON98-AUX	14-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
Ridgeline	2006-2007	HON03/PC-SON	14-Pin connector at headunit	AUX input only. Not compatible if factory XM is present.
S2000	2000-2003	HON98-AUX	14-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
S2000	2004-2007	HON03/PC-SON	14-Pin connector at headunit	Not compatible if factory XM is present.

Note 1: HON98-AUX - not compatible with 1995-Up Passport or models equipped with 6-disc in-dash radios.

Note 2: HON03/PC-SON also requires PIE Part # HON03-F/MM if vehicle is equipped with Navigation.

HUMMER

MAKE/MODEL	YEAR(S)	PIE Part #	LOCATION		NOTES
			Without XM	With XM	
H2	2003-2007	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.



DPX™ AUXILIARY INPUT CONVERTER APPLICATION GUIDE

PIE Auxiliary Input Converters allow you to convert the CD changer, Satellite radio or RSE port of your OEM radio into auxiliary input. Auxiliary devices such as Mobile Video Systems, MP3 and Digital Satellite Radio can be added to the OEM radio WITHOUT FM MODULATION, resulting in optimum sound quality.

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION		NOTES
			Without XM	With XM	
H2	2003-2007	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
H3	2005-2008	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
H3	2005-2008	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.

Note 1: GM12LAN-AUX/S requires separate harness - Is compatible with factory XM installed, and navigation radios.

Note 2: GM12-AUXv2 is compatible with factory XM installed and navigation radios.

JAGUAR

S Type	2000-2002	JAGW-AUX	12-Pin connector in trunk	Not compatible with 2003-2004 Jaguar S-Type.
S Type	2000-2002	JAG-AUX	12-Pin connector at headunit	Not compatible with 2003-2004 Jaguar S-Type.

JEEP

Cherokee	1996-1998	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Commander	2006-2007	CHRY04-AUX/S	10 & 22-Pin connectors at headunit	Compatible with REF, RAQ, RAK, REC radios only.
Commander	2006-2007	CHRY04-AUX	10 & 22-Pin connectors at headunit	Compatible with RAQ, RAK, REC radios only.
Compass	2007-2008	CHRY04-AUX/S	10 & 22-Pin connectors at headunit	Compatible with REF, RAQ, RAK, REC radios only.
Compass	2007-2008	CHRY04-AUX	10 & 22-Pin connectors at headunit	Compatible with RAQ, RAK, REC radios only.
Grand Cherokee	1996-1998	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Grand Cherokee	1999-2001	CHRY98-AUX	8-Pin connector at headunit	Must be 'Rounded Face' radio with 'CD-C' button.
Grand Cherokee	2002-2004	CHRY02-AUX	10-Pin connector at headunit	Not compatible with "RBQ", "RB4", "RAH", "REV" and "RBK" radios.
Grand Cherokee	2005-2007	CHRY04-AUX/S	10 & 22-Pin connectors at headunit	Compatible with REF, RAQ, RAK, REC radios only.
Grand Cherokee	2005-2007	CHRY04-AUX	10 & 22-Pin connectors at headunit	Compatible with RAQ, RAK, REC radios only.
Liberty	2002-2007	CHRY02-AUX	10-Pin connector at headunit	Radio must be CD Changer controller.
Patriot	2007-2008	CHRY04-AUX/S	10 & 22-Pin connectors at headunit	Compatible with REF, RAQ, RAK, REC radios only.
Patriot	2007-2008	CHRY04-AUX	10 & 22-Pin connectors at headunit	Compatible with RAQ, RAK, REC radios only.
Wrangler	1997-1998	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Wrangler	2002-2006	CHRY02-AUX	10-Pin connector at headunit	Not compatible with "RBQ", "RB4", "RAH", "REV" and "RBK" radios.

Note 1: CHRY98-AUX - must be 'Rounded Face' radio with 'CD-C' button.

Note 2: CHRY02-AUX not compatible if equipped with factory Satellite radio or external CD Changer (use PIE Part #'s X3 & X3-CHRY02 instead).

Note 3: CHRY02-AUX - not compatible with "RBQ" (6-disc in-dash), "RB4" (Navigation), "RAH", "REV" and "RBK" radios.

Note 4: CHRY-AUX - radio must be one of the following CD Changer controller headunits:

- 5-preset radio with 5-band EQ, "DISC ^" and "DISC v" on presets 1 and 5, and "MODE" button,
- 6-preset radio with Bass and Treble slider controls, "DIRECT DISC SELECT 1-6" printed above radio presets, and "MODE/EJECT" button.

Note 5: CHRY04-AUX/S not compatible if equipped with factory Satellite radio. Is compatible with factory VES installed.

Note 6: CHRY04-AUX not compatible if equipped with factory VES. Is compatible with factory Satellite radio installed.

LANDROVER

Discovery	1998-2003	LND/PC-SON	10-Pin connector under front passenger seat	
Freelander	2001-2002	LND/PC-SON	10-Pin connector under front passenger seat	
Freelander	2003-2004	LND/PC-SON	10-Pin connector at headunit	Visteon made radios only.
Range Rover	1998-2002	LND/PC-SON	10-Pin connector under front passenger seat	

LINCOLN

Aviator	2002-2003	FRDN-AUX	20-Pin connector at headunit	Use FRDW-AUX if pre-wired.
---------	-----------	----------	------------------------------	----------------------------



DPX™ AUXILIARY INPUT CONVERTER APPLICATION GUIDE

PIE Auxiliary Input Converters allow you to convert the CD changer, Satellite radio or RSE port of your OEM radio into auxiliary input. Auxiliary devices such as Mobile Video Systems, MP3 and Digital Satellite Radio can be added to the OEM radio WITHOUT FM MODULATION, resulting in optimum sound quality.

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION	NOTES
Aviator	2004-2005	FRD03-AUX	16 & 24-Pin connectors at headunit	Radio must be CD Changer capable.
Aviator	2004-2005	FRD03-AUX/S	16 & 24-Pin connectors at headunit	Radio must have "SAT" button.
Continental	1995-1997	FRDF-AUX	16-Pin connector at headunit	Premium Audio System.
Continental	1995-1997	FRDR-AUX	13 & 14-Pin connectors at RCU in trunk	JBL or LUX Audio System.
Continental	1998-2002	FRDN-AUX	20-Pin connector at headunit	Radio Series 870 – use FRDW-AUX if pre-wired.
LS	2000-2003	FRDN-AUX	20-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
LS	2004-2006	FRD03-AUX	16 & 24-Pin connectors at headunit	Use FRDW-AUX if pre-wired.
LS	2004-2006	FRD03-AUX/S	16 & 24-Pin connectors at headunit	Radio must have "SAT" button.
Mark VIII	1995-1998	FRDF-AUX	16-Pin connector at headunit	Radio must be CD Changer capable.
Mark LT	2006-2008	FRD04-AUX	16-Pin connector at headunit	Radio must have "AUX" button.
MKX	2007-2009	FRD04-AUX	16-Pin connector at headunit	Radio must have "AUX" button.
Navigator	1997-1998	FRDF-AUX	16-Pin connector at headunit	Radio must be CD Changer capable.
Navigator	1999-2002	FRDN-AUX	20-Pin connector at headunit	Radio must be CD Changer capable.
Navigator	2003	FRDN-AUX100	20-Pin connector at headunit	Not compatible if vehicle has factory DVD (RSE).
Navigator	2004-2005	FRD03-AUX100	16 & 24-Pin connectors at headunit	Not compatible if vehicle has factory DVD (RSE).
Navigator	2004-2006	FRD03-AUX/S	16 & 24-Pin connectors at headunit	Radio must have "SAT" button & no factory DVD (RSE).
Navigator	2007-2009	FRD04-AUX	16-Pin connector at headunit	Radio must have "AUX" button.
Town Car	1995-1997	FRDF-AUX	16-Pin connector at headunit	Premium Audio System.
Town Car	1995-1997	FRDR-AUX	13 & 14-Pin connectors at RCU in trunk	JBL or LUX Audio System.
Town Car	1998-2002	FRDW-AUX	12-Pin cable in trunk/center console	Use FRDN-AUX at headunit if not pre-wired.
Town Car	2003-2004	FRD03-AUX	16 & 24-Pin connectors at headunit	Use FRDW-AUX if pre-wired.
Town Car	2005-2006	FRD03-AUX/S	16 & 24-Pin connectors at headunit	Radio must have "SAT" button.
Zephyr	2006	FRD04-AUX	16-Pin connector at headunit	Radio must have "AUX" button.

Note 1: Not compatible with 2003 and up 6-disc headunits not equipped with external CD Changer capabilities.

Note 2: FRD04-AUX not compatible with factory navigation radios. Not compatible if equipped with factory Satellite radio or RSE (Rear Seat Entertainment) Not compatible with Ford Sync System.

Note 3: 2004 Models equipped with 6-Disc in-Dash, "THX Certified" Navigation radio may use Part # FRD03-AUX

Note 4: FRD03-AUX/S is not compatible with factory satellite or RSE (Rear Seat Entertainment) installed.

Note 5: FRD03-AUX/S is compatible with touch screen navigation radios, is not compatible with non-touch screen navigation radios.

MAZDA

Mazda 3	2004-2006	MAZ/PC-ALP	16-Pin connector at headunit	Application requires PIE part # ALP/M-RCA for AUX input.
Protégé	2001-2003	MAZ/PC-ALP	16-Pin connector at headunit	Application requires PIE part # ALP/M-RCA for AUX input.
Protégé 5	2001-2003	MAZ/PC-ALP	16-Pin connector at headunit	Application requires PIE part # ALP/M-RCA for AUX input.
RX8*	2004-2006	MAZ/PC-ALP	16-Pin connector at headunit	Application requires PIE part # ALP/M-RCA for AUX input.
Tribute	2001-2002	FRDN-AUX	20-Pin connector at headunit	Must be CD Changer capable.
Tribute	2003-2006	MAZ/PC-ALP	16-Pin connector at headunit	Application requires PIE part # ALP/M-RCA for AUX input.
Miata	2002-2006	MAZ/PC-ALP	16-Pin connector at headunit	Application requires PIE part # ALP/M-RCA for AUX input.
MPV	2002-2006	MAZ/PC-ALP	16-Pin connector at headunit	Application requires PIE part # ALP/M-RCA for AUX input.
B Series Truck	1995-1997	FRDF-AUX	16-Pin connector at headunit	Must be CD Changer capable.
B Series Truck	1998-2001	FRDN-AUX	20-Pin connector at headunit	Must be CD Changer capable.

*Note: RX8 requires radio firmware version 9.55 or greater. Press and hold "TEXT" button, while holding "TEXT" press and hold "PRESET#1" for a few seconds until version # appears on display.

MERCURY

Cougar	1999-2002	FRDC-AUX	12-Pin connector at headunit	Radio must be CD Changer capable.
--------	-----------	----------	------------------------------	-----------------------------------



DPX™ AUXILIARY INPUT CONVERTER APPLICATION GUIDE

PIE Auxiliary Input Converters allow you to convert the CD changer, Satellite radio or RSE port of your OEM radio into auxiliary input. Auxiliary devices such as Mobile Video Systems, MP3 and Digital Satellite Radio can be added to the OEM radio WITHOUT FM MODULATION, resulting in optimum sound quality.

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION	NOTES
Grand Marquis	1995-1997	FRDF-AUX	16-Pin connector at headunit	Radio Series 165 – Premium Audio System.
Grand Marquis	1995-1997	FRDR-AUX	13 & 14-Pin connectors at RCU in trunk	Radio Series 852 - JBL or LUX Audio System.
Grand Marquis	1998-2002	FRDN-AUX	20-Pin connector at headunit	Radio Series 870 - Use FRDW-AUX if pre-wired.
Grand Marquis	2003-2004	FRD03-AUX	16 & 24-Pin connectors at headunit	Use FRDW-AUX if pre-wired.
Grand Marquis	2005	FRD03-AUX/S	16 & 24-Pin connectors at headunit	Radio must have "SAT" button.
Marauder	2003-2004	FRD03-AUX	16 & 24-Pin connectors at headunit	Use FRDW-AUX if pre-wired.
Mariner	2005-2007	FRDN-AUX/S	16 & 20-Pin connectors at headunit	Radio must have "SAT" button.
Mariner	2005-2007	FRD03-AUX/S	16 & 24-Pin connectors at headunit	Radio must have "SAT" button.
Milan	2006-2009	FRD04-AUX	16-Pin connector at headunit	Radio must have "AUX" button.
Montego	2005-2006	Not Compatible		
Monterey	2005-2006	Not Compatible		
Mountaineer	1997	FRDR-AUX	13 & 14-Pin connectors at RCU in rear passenger panel	JBL or LUX Audio System.
Mountaineer	1997	FRDF-AUX	16-Pin connector at headunit	Premium Audio System.
Mountaineer	1998-2004	FRDN-AUX	20-Pin connector at headunit	Radio must be CD Changer capable.
Mountaineer	2004-2005	FRD03-AUX/S	16 & 24-Pin connectors at headunit	Radio must have "SAT" button.
Mountaineer	2006-2009	FRD04-AUX	16-Pin connector at headunit	Radio must have "AUX" button.
Sable	1996-2006	FRDR-AUX	13 & 14-Pin connectors at RCU in trunk	(Oval/Trapezoidal)
Tracer	1997-2002	FRDW-AUX	12-Pin connector in trunk or rear	Oval-face radio - use FRDF-AUX at headunit if not pre-wired.
Villager	1997-1998	FRDF-AUX	16-Pin connector at headunit	Radio must be CD Changer capable.
Villager*	1999-2002	FRDN-AUX	20-Pin connector at headunit	Radio must be CD Changer capable.

*Note: If the 2001-2002 Villager is equipped with factory video system use PIE Part # FRDW-AUX. (Factory pre-wire found in lower back section of radio dash console)

Note 1: Not compatible with 2003 and up 6-disc headunits not equipped with external CD Changer capabilities.

Note 2: FRD04-AUX not compatible with factory navigation radios. Not compatible if equipped with factory Satellite radio or RSE (Rear Seat Entertainment) Not compatible with Ford Sync System.

Note 3: 2004 Models equipped with 6-Disc in-Dash, "THX Certified" Navigation radio may use Part # FRD03-AUX

Note 4: FRD03-AUX/S is not compatible with factory satellite or RSE (Rear Seat Entertainment) installed.

Note 5: FRD03-AUX/S is compatible with touch screen navigation radios, is not compatible with non-touch screen navigation radios.

MINI

Cooper	2002-2006	BMW/PC-SON	3 & 6-Pin connectors in trunk	Vehicles without DSP ONLY.
--------	-----------	------------	-------------------------------	----------------------------

Note1: The BMW/PC-SON can be used as a CD Changer or Auxiliary input interface.

Note2: Not compatible if equipped with a factory external CD Changer.

MITSUBISHI

Eclipse	2003-2007	MIT-***	14 or 22-Pin connector at headunit	Radio must have auxiliary capabilities.
Endeavor	2003-2005	MIT-***	14 or 22-Pin connector at headunit	Radio must have auxiliary capabilities.
Grandis	2003-2007	MIT-***	14 or 22-Pin connector at headunit	Radio must have auxiliary capabilities.
Galant	2003-2007	MIT-***	14 or 22-Pin connector at headunit	Radio must have auxiliary capabilities.
Lancer	2003-2007	MIT-***	14 or 22-Pin connector at headunit	Radio must have auxiliary capabilities.
Lancer Evolution	2003-2007	MIT-***	14 or 22-Pin connector at headunit	Radio must have auxiliary capabilities.
Outlander	2003-2007	MIT-***	14 or 22-Pin connector at headunit	Radio must have auxiliary capabilities.
Spyder	2003-2007	MIT-***	14 or 22-Pin connector at headunit	Radio must have auxiliary capabilities.
Triton	2003-2007	MIT-***	14 or 22-Pin connector at headunit	Radio must have auxiliary capabilities.



DPX™ AUXILIARY INPUT CONVERTER APPLICATION GUIDE

PIE Auxiliary Input Converters allow you to convert the CD changer, Satellite radio or RSE port of your OEM radio into auxiliary input. Auxiliary devices such as Mobile Video Systems, MP3 and Digital Satellite Radio can be added to the OEM radio WITHOUT FM MODULATION, resulting in optimum sound quality.

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION	NOTES
------------	---------	-----------	----------	-------

→ *** at the end of part # indicates that part is available with female RCA audio plugs (MIT-RCA) or with male 3.5mm audio plug (MIT-3.5M).

Note 1: To determine if radio is auxiliary capable - Press and hold 'CD' button for 3-5 seconds until "AUX" is displayed.

Note 2: Not compatible if factory auxiliary input jack is present.

NISSAN

Quest	1997-1998	FRDF-AUX	16-Pin connector at headunit	Must be CD Changer controller headunit.
Quest	1999-2003	FRDN-AUX	20-Pin connector at headunit	Must be CD Changer controller headunit.
Quest	2004-Up	Not Compatible		

Note 1: If the 2001-2003 Quest is equipped with factory video system, use PIE Part # FRDW-AUX. (Factory pre-wire can be found in lower back section of radio dash console)

OLDSMOBILE

		PIE Part #	Without XM	With XM	
Achieva	1996-1998	GM10-AUX	N/A	N/A	Not compatible if equipped with factory external CD Changer.
Alero	1999-2000	GM10-AUX	N/A	N/A	Not compatible if equipped with factory external CD Changer.
Alero	2002-2004	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Alero	2004	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Aurora	1995-1999	GM10-AUX	N/A	N/A	Not compatible with 2000-Up Aurora.
Bravada	2002-2004	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Cutlass	1997-1999	GM10-AUX	N/A	N/A	Not compatible if equipped with factory external CD Changer.
Cutlass Supreme	1995-1997	GM10-AUX	N/A	N/A	Not compatible if equipped with factory external CD Changer.
Eighty-Eight	1996-1999	GM10-AUX	N/A	N/A	Not compatible if equipped with factory external CD Changer.
Intrigue	1998-2001	GM10-AUX	N/A	N/A	Not compatible if equipped with factory external CD Changer.
Intrigue	2002	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
LSS	1996-1999	GM10-AUX	N/A	N/A	Not compatible if equipped with factory external CD Changer.
Regency	1997-1998	GM10-AUX	N/A	N/A	Not compatible if equipped with factory external CD Changer.
Silhouette*	1996-1999	GM9-AUX	N/A	N/A	Not compatible with 2000-Up Silhouette.
Silhouette	2002-2004	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.

Note 1: Vehicles require GM factory CD data cable, Part # 12344003, if not pre-wired.

*Note 2: Radio must be AM/FM/Cassette with 'TAPE/AUX' button.

PLYMOUTH

Acclaim	1995	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Breeze	1996-2000	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Grand Voyager	1995-2000	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Neon	1995-2000	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Prowler	1997-2000	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.
Voyager	1995-2000	CHRY-AUX	8-Pin DIN connector at headunit	Not compatible if equipped with factory external CD Changer.

Note: Radio must be one of the following CD Changer controller headunits:

- 5-preset radio with 5-band EQ, "DISC A" and "DISC v" on presets 1 and 5, and "MODE" button,
- 6-preset radio with Bass and Treble slider controls, "DIRECT DISC SELECT 1-6", printed above radio presets, and "MODE/EJECT" button.

PONTIAC

		PIE Part #	Without XM	With XM	
Aztec	2002-2006	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Aztec	2003-2006	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Bonneville	1996-1999	GM9-AUX	N/A	N/A	Not compatible with 2000-Up Bonneville



DPX™ AUXILIARY INPUT CONVERTER APPLICATION GUIDE

PIE Auxiliary Input Converters allow you to convert the CD changer, Satellite radio or RSE port of your OEM radio into auxiliary input. Auxiliary devices such as Mobile Video Systems, MP3 and Digital Satellite Radio can be added to the OEM radio WITHOUT FM MODULATION, resulting in optimum sound quality.

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION		NOTES
			Without XM	With XM	
Firebird	1996-2002	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD Changer.
G6	2005-2006	Not Compatible			
GTO	2004-2006	Not Compatible			
Grand Am	1996-2000	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD Changer.
Grand Am	2002-2006	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Grand Am	2003-2006	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
Grand Prix	1996-2003	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD Changer.
Grand Prix	2004-2008	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Montana	1999	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD Changer.
Montana	2002-2007	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Montana	2004-2007	GM12LAN-AUX/S	N/A	GM12-X2	Must have factory XM Satellite installed.
Sunfire	1996-1999	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD Changer.
Sunfire	2002-2005	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Sunfire	2003-2005	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.
TransSport	1996-1998	GM9-AUX	N/A	N/A	Not compatible if equipped with factory external CD Changer.
Vibe	2003-2007	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.

Note 1: Pontiac radios AM/FM/SINGLE CD headunits use 9-Pin data port for an OEM cassette deck and are NOT compatible with the GM9-AUX.

Note 2: Pontiac radios 2000 and earlier are not capable of controlling two units; therefore, these radios will need to have the slave unit disconnected in order to use the GM9-AUX.

SATURN

		PIE Part #	Without XM	With XM	
All Models	1995-1999	GM10-AUX*	N/A	N/A	Not compatible with 2000-Up Saturn.
Relay	2005-2006	GM12-AUXv2	N/A	N/A	Must have XM Satellite / CD changer ready headunit.
Relay	2005-2006	GM12LAN-AUX/S	GM12-R1	GM12-X2	Must have XM Satellite ready headunit.

*Note: Requires Saturn Part # 21023550 and Part # 21023253 if not pre-wired.

SCION

tC	2004-2006	TOY03-AUX	12-Pin mini connector at headunit	Not compatible if factory Satellite radio is present.
tC	2004-2007	TOY03-AUX/S	12-Pin connector at headunit	Must have "SAT" button.
xA	2003-2006	TOY03-AUX	12-Pin mini connector at headunit	Not compatible if factory Satellite radio is present.
xA	2003-2007	TOY03-AUX/S	12-Pin connector at headunit	Must have "SAT" button.
xB	2003-2006	TOY03-AUX	12-Pin mini connector at headunit	Not compatible if factory Satellite radio is present.
xB	2003-2007	TOY03-AUX/S	12-Pin connector at headunit	Must have "SAT" button.

Note 1: Models equipped with OEM CD Changer may use PIE's X3 system to maintain function of CD Changer.

Note 2: TOY03-AUX is not compatible with navigation radios.

Note 3: Not compatible with OEL display radios.

TOYOTA

Avalon	1998-2002	TOY-AUX	12-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
Avalon	2003-2006	TOY03-AUX	12-Pin mini connector at headunit	Not compatible if equipped with factory external CD Changer.
Avalon	2005-2007	TOY03-AUX/S	12-Pin connector at headunit	Must have "SAT" button.
4Runner	1998-2002	TOY-AUX	12-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
4Runner	2003-2006	TOY03-AUX	12-Pin mini connector at headunit	Not compatible if equipped with factory external CD Changer.
4Runner	2006-2007	TOY03-AUX/S	12-Pin connector at headunit	Must have "SAT" button.



DPX™ AUXILIARY INPUT CONVERTER APPLICATION GUIDE

PIE Auxiliary Input Converters allow you to convert the CD changer, Satellite radio or RSE port of your OEM radio into auxiliary input. Auxiliary devices such as Mobile Video Systems, MP3 and Digital Satellite Radio can be added to the OEM radio WITHOUT FM MODULATION, resulting in optimum sound quality.

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION	NOTES
Camry	1998-2004	TOY-AUX	12-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
Camry	2005-2007	TOY03-AUX	12-Pin mini connector at headunit	Not compatible if equipped with factory external CD Changer.
Camry	2005-2007	TOY03-AUX/S	12-Pin connector at headunit	Must have "SAT" button.
Camry Solara	2000-2002	TOY-AUX	12-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
Camry Solara	2003-2007	TOY03-AUX	12-Pin mini connector at headunit	Not compatible if equipped with factory external CD Changer.
Camry Solara	2005-2007	TOY03-AUX/S	12-Pin connector at headunit	Must have "SAT" button.
Celica	1998-2002	TOY-AUX	12-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
Celica	2003-2005	TOY03-AUX	12-Pin mini connector at headunit	Not compatible if equipped with factory external CD Changer.
Corolla	1998-2004	TOY-AUX	12-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
Corolla	2005-2007	TOY03-AUX	12-Pin mini connector at headunit	Not compatible if equipped with factory external CD Changer.
FJ Cruiser	2007-2008	TOY03-AUX/S	12-Pin connector at headunit	Must have "SAT" button.
Highlander	2001-2003	TOY-AUX	12-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
Highlander	2004-2008	TOY03-AUX	12-Pin mini connector at headunit	Not compatible if equipped with factory external CD Changer.
Highlander	2006-2008	TOY03-AUX/S	12-Pin connector at headunit	Must have "SAT" button.
Highlander Hybrid	2007-2008	TOY03-AUX/S	12-Pin connector at headunit	Must have "SAT" button.
Land Cruiser	1998-2002	TOY-AUX	12-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
Land Cruiser	2003-2007	TOY03-AUX	12-Pin mini connector at headunit	Not compatible if equipped with factory external CD Changer.
Land Cruiser	2005-2007	TOY03-AUX/S	12-Pin connector at headunit	Must have "SAT" button.
Matrix	2005-2006	TOY03-AUX	12-Pin mini connector at headunit	Not compatible if equipped with factory external CD Changer.
MR2	1998-2002	TOY-AUX	12-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
MR2	2003-2005	TOY03-AUX	12-Pin mini connector at headunit	Not compatible if equipped with factory external CD Changer.
Prius	2006-2007	TOY03-AUX/S	12-Pin connector at headunit	Must have "SAT" button.
RAV4	1998-2005	TOY-AUX	12-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
RAV4	2006-2007	TOY03-AUX/S	12-Pin connector at headunit	Must have "SAT" button.
Sequoia	2000-2002	TOY-AUX	12-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
Sequoia	2003-2006	TOY03-AUX	12-Pin mini connector at headunit	Not compatible if equipped with factory external CD Changer.
Sequoia	2006-2007	TOY03-AUX/S	12-Pin connector at headunit	Must have "SAT" button.
Sienna	1998-2003	TOY-AUX	12-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
Sienna	2004-2007	TOY03-AUX	12-Pin mini connector at headunit	Not compatible if equipped with factory external CD Changer.
Sienna	2006-2007	TOY03-AUX/S	12-Pin connector at headunit	Must have "SAT" button.
Solara	2005-2007	TOY03-AUX/S	12-Pin connector at headunit	Must have "SAT" button.
Tacoma	1998-2004	TOY-AUX	12-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
Tacoma	2005-2008	TOY03-AUX	12-Pin mini connector at headunit	Not compatible if equipped with factory external CD Changer.
Tacoma	2005-2008	TOY03-AUX/S	12-Pin mini connector at headunit	Must have "SAT" button.
Tundra	2000-2002	TOY-AUX	12-Pin connector at headunit	Not compatible if equipped with factory external CD Changer.
Tundra	2003-2008	TOY03-AUX	12-Pin mini connector at headunit	Not compatible if equipped with factory external CD Changer.
Tundra	2003-2008	TOY03-AUX/S	12-Pin mini connector at headunit	Must have "SAT" button.
Yaris	2007	TOY03-AUX	12-Pin mini connector at headunit	Not compatible if equipped with factory external CD Changer.

Note 1: TOY03-AUX/S - not compatible if factory satellite is present, is compatible with Navigation radio - must have "SAT" button.

Note 2: For models equipped with OEM CD/DVD-Changer or factory Satellite radio, use PIE's X3 system to maintain function of CD Changer/Satellite.

Note 3: TOY03-AUX - not compatible with factory navigation radio or if factory external CD changer in present.

VOLKSWAGEN

Beetle	1998-2008	VWR-AUX*	8-Pin connector at headunit	Use PIE Part# VW-AUX if vehicle is pre-wired with 12-Pin connector.
Cabrio	1998-2002	VWR-AUX*	8-Pin connector at headunit	Use PIE Part# VW-AUX if vehicle is pre-wired with 12-Pin connector.
Eurovan	1999-2003	VWR-AUX*	8-Pin connector at headunit	Use PIE Part# VW-AUX if vehicle is pre-wired with 12-Pin connector.
Golf	1998-2002	VWR-AUX*	8-Pin connector at headunit	Use PIE Part# VW-AUX if vehicle is pre-wired with 12-Pin connector.



DPX™ AUXILIARY INPUT CONVERTER APPLICATION GUIDE

PIE Auxiliary Input Converters allow you to convert the CD changer, Satellite radio or RSE port of your OEM radio into auxiliary input. Auxiliary devices such as Mobile Video Systems, MP3 and Digital Satellite Radio can be added to the OEM radio WITHOUT FM MODULATION, resulting in optimum sound quality.

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION	NOTES
Golf	2003-2007	VW02-AUX	12-Pin connector at headunit. Double DIN radio only.	Use PIE Part# VW-AUX if vehicle is pre-wired with 12-Pin connector.
GTI	1999-2002	VWR-AUX*	8-Pin connector at headunit	Use PIE Part# VW-AUX if vehicle is pre-wired with 12-Pin connector.
Jetta	1998-2001	VWR-AUX*	8-Pin connector at headunit	Use PIE Part# VW-AUX if vehicle is pre-wired with 12-Pin connector.
Jetta	2002-2007	VW02-AUX	12-Pin connector at headunit. Double DIN radio only.	Use PIE Part# VW-AUX if vehicle is pre-wired with 12-Pin connector.
Passat	1998-2002	VWR-AUX*	8-Pin connector at headunit	Use PIE Part# VW-AUX if vehicle is pre-wired with 12-Pin connector.
Passat	2003-2007	VW02-AUX	12-Pin connector at headunit. Double DIN radio only.	Use PIE Part# VW-AUX if vehicle is pre-wired with 12-Pin connector.
Touareg	2004-2006	VW02-AUX	12-Pin connector at headunit. Double DIN radio only.	Use PIE Part# VW-AUX if vehicle is pre-wired with 12-Pin connector.

Note 1: Not compatible with Navigation radios (excluding Touareg), not compatible if factory satellite or external CD changer is present.
*Note 2: Use PIE Part # X3 & X3-VWR for vehicles equipped with a factory external CD Changer or Satellite.