



iPod INTERFACE FOR OEM CD 'CHANGER READY' OR 'SATELLITE READY' HEADUNITS

PIE iPod interfaces are designed to allow control of your iPod (songs, playlists, etc) through either the CD changer mode or satellite radio mode of the OEM headunit, provide digital quality sound, and at the same time keep your iPod charged. Three methods of iPod control are made possible with our "POD", "POD2", and "POD/S" line of interfaces depending on your iPod display and control preferences.

"POD" - (Replaces external factory CD changer, if present) - Allows track up/down, FF, REW, Shuffle, and direct access to 6 iPod playlists from the OEM headunit (iPod screen and controls are disabled).

"POD2" - (Replaces external factory CD changer, if present) - Allows track up/down, FF, and REW from the OEM headunit and retains iPod screen and controls.

"POD/S" - (Uses satellite controls) - Allows full control of the iPod and displays iPod text information on the radio display using the Satellite radio mode of the OEM headunit.

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION	NOTES
<u>ACURA</u>				
Integra	1992-2001	HON/PC-POD(2)	8-Pin connector in trunk	
Legend	1992-1995	HON/PC-POD(2)	8-Pin connector in trunk	
Vigor	1992-1994	HON/PC-POD(2)	8-Pin connector in trunk	
CL	1997-1999	HON/PC-POD(2)	8-Pin connector in trunk	
CL	2001-2003	Not Compatible		
TL	1995-1998	HON/PC-POD(2)	8-Pin connector in trunk	
3.2TL	1999-2006	Not Compatible		
MDX	2001-2006	Not Compatible		
NSX	1992-2005	Not Compatible		
RL	1996-2001	HON/PC-POD(2)	8-Pin connector in trunk	Not compatible if equipped with factory Navigation.
RL	2002-2006	Not Compatible		
RSX	2002-2006	Not Compatible		
SLX	1996-1999	Not Compatible		
TSX	2004-2006	Not Compatible		

Note: Not compatible if equipped with a factory external CD Changer.

<u>AUDI</u>				
A3	2006-2007	VWR/PC-POD(2)*	8-Pin connector at headunit	Use Part # AUD/PC-POD(2) if pre-wired with 13-Pin DIN connector.
A4	1998-2006	VWR/PC-POD(2)	8-Pin connector at headunit	Use Part # AUD/PC-POD(2) if pre-wired with 13-Pin DIN connector.
A4	2007	VW02/PC-POD(2)*	8-Pin connector at headunit	Use Part # AUD/PC-POD(2) if pre-wired with 13-Pin DIN connector.
A6	1998-2005	VWR/PC-POD(2)	8-Pin connector at headunit	Use Part # AUD/PC-POD(2) if pre-wired with 13-Pin DIN connector.
A8	1998-2005	VWR/PC-POD(2)	8-Pin connector at headunit	Use Part # AUD/PC-POD(2) if pre-wired with 13-Pin DIN connector.
Allroad	2001-2005	VWR/PC-POD(2)	8-Pin connector at headunit	Use Part # AUD/PC-POD(2) if pre-wired with 13-Pin DIN connector.
Cabriolet	1998	VWR/PC-POD(2)	8-Pin connector at headunit	Use Part # AUD/PC-POD(2) if pre-wired with 13-Pin DIN connector.
RS6	2003	VWR/PC-POD(2)	8-Pin connector at headunit	Use Part # AUD/PC-POD(2) if pre-wired with 13-Pin DIN connector.
S4	2000-2005	VWR/PC-POD(2)	8-Pin connector at headunit	Use Part # AUD/PC-POD(2) if pre-wired with 13-Pin DIN connector.
S6	2002-2003	VWR/PC-POD(2)	8-Pin connector at headunit	Use Part # AUD/PC-POD(2) if pre-wired with 13-Pin DIN connector.
S8	2001-2003	VWR/PC-POD(2)	8-Pin connector at headunit	Use Part # AUD/PC-POD(2) if pre-wired with 13-Pin DIN connector.
TT	2000-2005	VWR/PC-POD(2)	8-Pin connector at headunit	Use Part # AUD/PC-POD(2) if pre-wired with 13-Pin DIN connector.
A6 / A8 / Q7	2006-UP	Not Compatible		

*Note : Requires AA3-HAR if not pre-wired.

Note 1: Not compatible if equipped with a factory External CD Changer or Satellite.

Note 2: 2001 and up models equipped with the "Symphony II" (6-disc in-dash) headunit or radios using 20-pin one piece connector will also require PIE Part # AA3-HAR.

Note 3: VWR and AUD part are not compatible if vehicle is equipped with factory Navigation, Satellite, or external CD changer.



**iPod INTERFACE FOR OEM CD 'CHANGER READY' OR
'SATELLITE READY' HEADUNITS**

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION		NOTES
<u>BUICK</u>					
		PIE Part #	Without XM	With XM	
Enclave	2007-2008	GMLAN-POD/S	GMLAN-R1	GMLAN-X1	Must have 'CAT' button.
Enclave	2007-2008	GM2L-POD/S	GM2L-R01	GM2L-X01	Must have 'CAT' button.
La Crosse	2005-2007	GM12-POD/S	GM12-R1	GM12-X1	Must have 'BAND' button.
La Crosse	2005-2007	GM2L-POD/S	GM2L-R03	GM2L-X03	Must have 'BAND' button.
Lucerne	2006-2007	GMLAN-POD/S	GMLAN-R1	GMLAN-X1	Must have 'CAT' button.
Lucerne	2006-2007	GM2L-POD/S	GM2L-R01	GM2L-X01	Must have 'CAT' button.
Rainier	2004-2007	GM12-POD/S	GM12-R1	GM12-X1	Must have 'BAND' button.
Rainier	2004-2007	GM2L-POD/S	GM2L-R03	GM2L-X03	Must have 'BAND' button.
Rendezvous	2003-2007	GM12-POD/S	GM12-R1	GM12-X1	Must have 'BAND' button.
Rendezvous	2003-2007	GM2L-POD/S	GM2L-R03	GM2L-X03	Must have 'BAND' button.
Terraza	2005-2007	GM12-POD/S	GM12-R1	GM12-X1	Must have 'BAND' button.
Terraza	2005-2007	GM2L-POD/S	GM2L-R03	GM2L-X03	Must have 'BAND' button.

Note: Must be XM capable radio.

<u>CADILLAC</u>					
		PIE Part #	Without XM	With XM	
DTS	2007-2008	GMLAN-POD/S	Not Available	GMLAN-X1	Must have 'CAT' button.
DTS	2007-2008	GM2L-POD/S	Not Available	GM2L-X01	Must have 'CAT' button.
Escalade	2003-2006	GM12-POD/S	GM12-R1	GM12-X1	Must have 'BAND' button.
Escalade	2003-2006	GM2L-POD/S	GM2LR03	GM2L-X03	Must have 'BAND' button.
Escalade	2007-2008	GMLAN-POD/S	GMLAN-R1	GMLAN-X1	Must have 'CAT' button.
Escalade	2007-2008	GM2L-POD/S	GM2L-R01	GM2L-X01	Must have 'CAT' button.
SRX	2004-2006	GM12-POD/S	Not Available	GM12-X1	Must have 'CAT' button.
SRX	2004-2006	GM2L-POD/S	Not Available	GM2L-X03	Must have 'CAT' button.
SRX	2007-2008	GMLAN-POD/S	GMLAN-R1	GMLAN-X1	Must have 'CAT' button.
SRX	2007-2008	GM2L-POD/S	GM2L-R01	GM2L-X01	Must have 'CAT' button.

Note: Must be XM capable radio.

<u>CHEVROLET</u>					
		PIE Part #	Without XM	With XM	
Avalanche	2003-2006	GM12-POD/S	GM12-R1	GM12-X1	Must have 'BAND' button.
Avalanche	2003-2006	GM2L-POD/S	GM2L-R03	GM2L-X03	Must have 'BAND' button.
Avalanche	2007-2008	GMLAN-POD/S	GMLAN-R1	GMLAN-X1	Must have 'CAT' button.
Avalanche	2007-2008	GM2L-POD/S	GM2L-R01	GM2L-X01	Must have 'CAT' button.
Cavalier	2003-2005	GM12-POD/S	GM12-R1	GM12-X1	Must have 'BAND' button.
Cavalier	2003-2005	GM2L-POD/S	GM2L-R03	GM2L-X03	Must have 'BAND' button.
Cobalt	2005-2006	GM2L-POD/S	GM2L-R05	GM2L-X02	Must have 'BAND' button.
Cobalt	2007-2008	GM2L-POD/S	GM2L-R02	GM2L-X02	Must have 'CAT' button.
Colorado	2004-2008	GM12-POD/S	GM12-R1	GM12-X1	Must have 'BAND' button.
Colorado	2004-2008	GM2L-POD/S	GM2L-R03	GM2L-X03	Must have 'BAND' button.
Corvette	2005-2008	GM12-POD/S	GM12-R1	GM12-X1	Must have 'BAND' button.
Corvette	2005-2008	GM2L-POD/S	GM2L-R03	GM2L-X03	Must have 'BAND' button.
HHR	2006-2007	GM2L-POD/S	GM2L-R02	GM2L-X02	Must have 'CAT' button.
Equinox	2005-2006	GM2L-POD/S	GM2L-R04	GM2L-X03	Must have 'XM/ AUX' button.
Equinox	2007	GM2L-POD/S	GM2L-R02	GM2L-X02	Silver face radio with 'CAT' button.
Impala	2004-2005	GM12-POD/S	GM12-R1	GM12-X1	Must have 'BAND' button.
Impala	2004-2005	GM2L-POD/S	GM2L-R03	GM2L-X03	Must have 'BAND' button.



**iPod INTERFACE FOR OEM CD 'CHANGER READY' OR
'SATELLITE READY' HEADUNITS**

MAKE/MODEL	YEAR(S)	PIE PART#		LOCATION		NOTES
		PIE Part #	Without XM	With XM		
Impala	2006-2008	GMLAN-POD/S	GMLAN-R1	GMLAN-X1		Must have 'CAT' button.
Impala	2006-2008	GM2L-POD/S	GM2L-R01	GM2L-X01		Must have 'CAT' button.
Malibu/Max	2004-2008	GM2L-POD/S	GM2L-R05	GM2L-X02		Must have 'BAND' button.
Monte Carlo	2003-2005	GM12-POD/S	GM12-R1	GM12-X1		Must have 'BAND' button.
Monte Carlo	2003-2005	GM2L-POD/S	GM2L-R03	GM2L-X03		Must have 'BAND' button.
Monte Carlo	2006-2007	GMLAN-POD/S	GMLAN-R1	GMLAN-X1		Must have 'CAT' button.
Monte Carlo	2006-2007	GM2L-POD/S	GM2L-R01	GM2L-X01		Must have 'CAT' button.
Silverado	2003-2006	GM12-POD/S	GM12-R1	GM12-X1		Must have 'BAND' button.
Silverado	2003-2006	GM2L-POD/S	GM2L-R03	GM2L-X03		Must have 'BAND' button.
Silverado Classic	2007	GM12-POD/S	GM12-R1	GM12-X1		Must have 'BAND' button.
Silverado Classic	2007	GM2L-POD/S	GM2L-R03	GM2L-X03		Must have 'BAND' button.
Silverado New Body	2007-2008	GMLAN-POD/S	GMLAN-R1	GMLAN-X1		Must have 'CAT' button.
Silverado New Body	2007-2008	GM2L-POD/S	GM2L-R01	GM2L-X01		Must have 'CAT' button.
Suburban	2003-2006	GM12-POD/S	GM12-R1	GM12-X1		Must have 'BAND' button.
Suburban	2003-2006	GM2L-POD/S	GM2L-R03	GM2L-X03		Must have 'BAND' button.
Suburban	2007-2008	GMLAN-POD/S	GMLAN-R1	GMLAN-X1		Must have 'CAT' button.
Suburban	2007-2008	GM2L-POD/S	GM2L-R01	GM2L-X01		Must have 'CAT' button.
Tahoe	2003-2006	GM12-POD/S	GM12-R1	GM12-X1		Must have 'BAND' button.
Tahoe	2003-2006	GM2L-POD/S	GM2L-R03	GM2L-X03		Must have 'BAND' button.
Tahoe	2007-2008	GMLAN-POD/S	GMLAN-R1	GMLAN-X1		Must have 'CAT' button.
Tahoe	2007-2008	GM2L-POD/S	GM2L-R01	GM2L-X01		Must have 'CAT' button.
Trailblazer	2004-2008	GM12-POD/S	GM12-R1	GM12-X1		Must have 'BAND' button.
Trailblazer	2004-2008	GM2L-POD/S	GM2L-R03	GM2L-X03		Must have 'BAND' button.
Uplander	2005-2008	GM12-POD/S	GM12-R1	GM12-X1		Must have 'BAND' button.
Uplander	2005-2008	GM2L-POD/S	GM2L-R03	GM2L-X03		Must have 'BAND' button.
Venture	2004-2005	GM12-POD/S	Not Available	GM12-X1		Must have factory XM Satellite installed.
Venture	2004-2005	GM2L-POD/S	Not Available	GM2L-X03		Must have factory XM Satellite installed.

Note: Must be XM capable radio.

CHRYSLER

300	2005-2007	CHRY04/PC-POD2	10 & 22-Pin connectors at headunit		Compatible with RAQ, RAK, REC radios only.
300C	2005-2007	CHRY04/PC-POD2	10 & 22-Pin connectors at headunit		Compatible with RAQ, RAK, REC radios only.
300M	1999-2000	CHRY/PC-POD(2)	8-Pin connector at headunit		
300M	2001	CHRY98/PC-POD(2)	8-Pin connector at headunit		
300M	2002-2004	CHRY02/PC-POD(2)	10-Pin connector at headunit		Not compatible with "RBQ", "RB4", "RAH" and "REV" radios.
Aspen	2007	CHRY04/PC-POD2	10 & 22-Pin connectors at headunit		Compatible with RAQ, RAK, REC radios only.
Cirrus	1995-2000	CHRY/PC-POD(2)	8-Pin connector at headunit		
Concorde	1995-2000	CHRY/PC-POD(2)	8-Pin connector at headunit		
Concorde	2001	CHRY98/PC-POD(2)	8-Pin connector at headunit		
Concorde	2002-2005	CHRY02/PC-POD(2)	10-Pin connector at headunit		Not compatible with "RBQ", "RB4", "RAH" and "REV" radios.
Crossfire	2004-2006	Not Compatible			
Grand Voyager	2000	CHRY/PC-POD(2)	8-Pin connector at headunit		
LeBaron	1995	CHRY/PC-POD(2)	8-Pin connector at headunit		
LHS	1995-2000	CHRY/PC-POD(2)	8-Pin connector at headunit		
LHS	2001	CHRY98/PC-POD(2)	8-Pin connector at headunit		
LHS	2002-2004	CHRY02/PC-POD(2)	10-Pin connector at headunit		Not compatible with "RBQ", "RB4", "RAH" and "REV" radios.
New Yorker	1995-1996	CHRY/PC-POD(2)	8-Pin connector at headunit		



iPod INTERFACE FOR OEM CD 'CHANGER READY' OR 'SATELLITE READY' HEADUNITS

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION	NOTES
Pacifica	2003-2008	CHRY02/PC-POD(2)	10-Pin connector at headunit	Not compatible with "RBQ", "RB4", "RAH" and "REV" radios.
PT Cruiser	2001	CHRY98/PC-POD(2)	8-Pin connector at headunit	
PT Cruiser	2002-2005	CHRY02/PC-POD(2)	10-Pin connector at headunit	Not compatible with "RBQ", "RB4", "RAH" and "REV" radios.
PT Cruiser	2006-2008	CHRY04/PC-POD2	10 & 22-Pin connectors at headunit	Compatible with RAQ, RAK, REC radios only.
Sebring	1995-2000	CHRY/PC-POD(2)	8-Pin connector at headunit	
Sebring	2001	CHRY98/PC-POD(2)	8-Pin connector at headunit	
Sebring	2002-2006	CHRY02/PC-POD(2)	10-Pin connector at headunit	Not compatible with "RBQ", "RB4", "RAH" and "REV" radios.
Town & Country	1995-2000	CHRY/PC-POD(2)	8-Pin connector at headunit	
Town & Country	2001	CHRY98/PC-POD(2)	8-Pin connector at headunit	
Town & Country	2002-2007	CHRY02/PC-POD(2)	10-Pin connector at headunit	Not compatible with "RBQ", "RB4", "RAH" and "REV" radios.
Voyager	2000	CHRY/PC-POD(2)	8-Pin connector at headunit	
Voyager	2001	CHRY98/PC-POD(2)	8-Pin connector at headunit	
Voyager	2002-2004	CHRY02/PC-POD(2)	10-Pin connector at headunit	Not compatible with "RBQ", "RB4", "RAH" and "REV" radios.

Note 1: Not compatible if equipped with a factory external CD Changer.

Note 2: CHRY98/PC-POD(2) - Must be 'Rounded Face' radio with 'CD-C' button.

Note 3: CHRY02/PC-POD(2) - Must be 'Rounded Face' radio with 'MODE' button.

Note 4: CHRY02/PC-POD(2) not compatible if equipped with factory Satellite radio.

Note 5: Radio must be one of the following CD Changer controller headunits:

- 5-preset radio with 5-band EQ, "DISC ^" and "DISC v" on presets 1 and 5, and "MODE" button,
- 6-preset radio with Bass and Treble slider controls, "DIRECT DISC SELECT 1-6", printed above radio presets, and "MODE/EJECT" button.

Note 6: CHRY04/PC-POD2 is not compatible with factory VES installed. Is compatible with factory satellite installed.

DODGE

Avenger	1995-2000	CHRY/PC-POD(2)	8-Pin connector at headunit	
Caliber	2007-2008	CHRY04/PC-POD2	10 & 22-Pin connectors at headunit	Compatible with RAQ, RAK, REC radios only.
Caravan	1995-2000	CHRY/PC-POD(2)	8-Pin connector at headunit	
Caravan	2001	CHRY98/PC-POD(2)	8-Pin connector at headunit	
Caravan	2002-2007	CHRY02/PC-POD(2)	10-Pin connector at headunit	Not compatible with "RBQ", "RB4", "RAH" and "REV" radios.
Charger	2006-2007	CHRY04/PC-POD2	10 & 22-Pin connectors at headunit	Compatible with RAQ, RAK, REC radios only.
Dakota	1995-2000	CHRY/PC-POD(2)	8-Pin connector at headunit	
Dakota	2001	CHRY98/PC-POD(2)	8-Pin connector at headunit	
Dakota	2002-2004	CHRY02/PC-POD(2)	10-Pin connector at headunit	Not compatible with "RBQ", "RB4", "RAH" and "REV" radios.
Dakota	2005-2008	CHRY04/PC-POD2	10 & 22-Pin connectors at headunit	Compatible with RAQ, RAK, REC radios only.
Durango	1998-2000	CHRY/PC-POD(2)	8-Pin connector at headunit	
Durango	2001	CHRY98/PC-POD(2)	8-Pin connector at headunit	
Durango	2002-2003	CHRY02/PC-POD(2)	10-Pin connector at headunit	Not compatible with "RBQ", "RB4", "RAH" and "REV" radios.
Durango	2004-2007	CHRY04/PC-POD2	10 & 22-Pin connectors at headunit	Compatible with RAQ, RAK, REC radios only.
Grand Caravan	1995-2000	CHRY/PC-POD(2)	8-Pin connector at headunit	
Intrepid	1995-2000	CHRY/PC-POD(2)	8-Pin connector at headunit	
Intrepid	2001	CHRY98/PC-POD(2)	8-Pin connector at headunit	
Intrepid	2002-2004	CHRY02/PC-POD(2)	10-Pin connector at headunit	Not compatible with "RBQ", "RB4", "RAH" and "REV" radios.
Magnum	2005-2007	CHRY04/PC-POD2	10 & 22-Pin connectors at headunit	Compatible with RAQ, RAK, REC radios only.
Neon	1995-2000	CHRY/PC-POD(2)	8-Pin connector at headunit	
Neon	2001	CHRY98/PC-POD(2)	8-Pin connector at headunit	
Neon	2002-2005	CHRY02/PC-POD(2)	10-Pin connector at headunit	Not compatible with "RBQ", "RB4", "RAH" and "REV" radios.
Pickup	1995-2000	CHRY/PC-POD(2)	8-Pin connector at headunit	
Ram	1995-2000	CHRY/PC-POD(2)	8-Pin connector at headunit	



iPod INTERFACE FOR OEM CD 'CHANGER READY' OR 'SATELLITE READY' HEADUNITS

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION	NOTES
Ram	2001	CHRY98/PC-POD(2)	8-Pin connector at headunit	Not compatible with "RBQ", "RB4", "RAH" and "REV" radios. Compatible with RAQ, RAK, REC radios only.
Ram	2002-2005	CHRY02/PC-POD(2)	10-Pin connector at headunit	
Ram	2006-2008	CHRY04/PC-POD2	10 & 22-Pin connectors at headunit	
Spirit	1995	CHRY/PC-POD(2)	8-Pin connector at headunit	
Stealth	1995-1996	CHRY/PC-POD(2)	8-Pin connector at headunit	
Stratus	1995-2000	CHRY/PC-POD(2)	8-Pin connector at headunit	
Stratus	2001	CHRY98/PC-POD(2)	8-Pin connector at headunit	
Stratus	2002-2006	CHRY02/PC-POD(2)	10-Pin connector at headunit	
Viper	1995-2000	CHRY/PC-POD(2)	8-Pin connector at headunit	

Note 1: Not compatible if equipped with a factory external CD Changer.

Note 2: CHRY98/PC-POD(2) - Must be 'Rounded Face' radio with 'CD-C' button.

Note 3: CHRY02/PC-POD(2) - Must be 'Rounded Face' radio with 'MODE' button.

Note 4: CHRY02/PC-POD(2) not compatible if equipped with factory Satellite radio.

Note 5: Radio must be one of the following CD Changer controller headunits:

- 5-preset radio with 5-band EQ, "DISC ^" and "DISC v" on presets 1 and 5, and "MODE" button,
- 6-preset radio with Bass and Treble slider controls, "DIRECT DISC SELECT 1-6", printed above radio presets, and "MODE/EJECT" button.

Note 6: CHRY04/PC-POD2 is not compatible with factory VES installed. Is compatible with factory satellite installed.

EAGLE

Summit	1995-1996	CHRY/PC-POD(2)	8-Pin connector at headunit
Talon	1995-1998	CHRY/PC-POD(2)	8-Pin connector at headunit
Vision	1995-1997	CHRY/PC-POD(2)	8-Pin connector at headunit

Note: Radio must be one of the following CD Changer controller headunits:

- 5-preset radio with 5-band EQ, "DISC ^" and "DISC v" on presets 1 and 5, and "MODE" button,
- 6-preset radio with Bass and Treble slider controls, "DIRECT DISC SELECT 1-6", printed above radio presets, and "MODE/EJECT" button.

FORD

2004 Models equipped with 6-Disc in-Dash, THX certified. Navigation radio may use Part # FRD03/PC-POD(2)

Crown Victoria	1995-1997	FRDF/PC-POD(2)	16-Pin connector at headunit	Premium Audio System.
Crown Victoria	1995-1997	FRDR/PC-POD(2)	RCU in rear driver side panel	JBL or LUX Audio System.
Crown Victoria	1998-2002	FRDN/PC-POD(2)	20-Pin connector at headunit	Must be CD Changer controlling radio.
Crown Victoria	2003-2004	FRD03/PC-POD(2)	16 & 24 Pin connectors at H/U	Must be CD Changer controlling radio.
Crown Victoria	2005-2006	FRD03-POD/S	16 & 24 Pin connectors at H/U	Radio must have "SAT" button.
Econoline	1997	FRDF/PC-POD(2)	16-Pin connector at headunit	Must be CD Changer controlling radio.
Econoline	1998-2005	FRDN/PC-POD(2)	20-Pin connector at headunit	Must be CD Changer controlling radio.
Econoline	2006-2008	FRDN-POD/S	20-Pin connector at headunit	Radio must have "SAT" button & no factory DVD (RSE).
Edge	2007-2010	FRD04-POD/S	16-Pin connector at headunit	Not compatible with factory Satellite, RSE or Navigation.
Escape	2001-2007	FRDN/PC-POD(2)	20-Pin connector at headunit	Not compatible with 5L8T-18C815-EC radio model.
Escape	2004-2005	FRD03/PC-POD(2)	16 & 24 Pin connectors at H/U	Radio Model 3L8T-18C815-FB.
Escape	2004-2005	FRDN-POD/S	20-Pin connector at headunit	Radio must have "SAT" button.
Escape	2004-2005	FRD03-POD/S	16 & 24 Pin connectors at H/U	Radio must have "SAT" button.
Escape Hybrid	2006-2007	FRDN-POD/S	20-Pin connector at headunit	Non-navigation radio. Radio must have "SAT" button.
Escape Hybrid	2006-2007	FRD03-POD/S	16 & 24 Pin connectors at H/U	Non-navigation radio. Radio must have "SAT" button.
Escape Hybrid	2006-2007	FRDC/PC-POD(2)	12-Pin connector at headunit	Navigation radio only (takes place of OEM changer).
Escape Hybrid	2006-2007	FRDW/PC-POD(2)	12-Pin data cable under passenger seat	Navigation radio only (takes place of OEM changer).
Escort	1997-2003	FRDW/PC-POD(2)	12-Pin data cable in trunk/rear	Use FRDF/PC-POD(2) at headunit if not pre-wired.
Excursion	2000-2005	FRDN/PC-POD(2)	20-Pin connector at headunit	Must be CD Changer controlling radio.
Expedition	1997-1998	FRDF/PC-POD(2)	16-Pin connector at headunit	Must be CD Changer controlling radio.
Expedition	1999-2002	FRDN/PC-POD(2)	20-Pin connector at headunit	Must be CD Changer controlling radio.
Expedition	2004-2006	FRD03-POD/S	16 & 24 Pin connectors at H/U	Radio must have "SAT" button & no factory DVD (RSE).



iPod INTERFACE FOR OEM CD 'CHANGER READY' OR 'SATELLITE READY' HEADUNITS

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION	NOTES
Expedition	2007-2009	FRD04-POD/S	16- Pin connector at headunit	Not compatible with factory Satellite, RSE or Navigation.
Explorer	1995-1997	FRDF/PC-POD(2)	16-Pin connector at headunit	Premium Audio System.
Explorer	1995-1997	FRDR/PC-POD(2)	RCU in rear passenger side panel	JBL or LUX Audio System.
Explorer	1998-2004	FRDN/PC-POD(2)	20-Pin connector at headunit	Must be CD Changer controlling radio.
Explorer	2004-2005	FRDN-POD/S	20-Pin connector at headunit	Radio must have "SAT" button & no factory DVD (RSE).
Explorer	2004-2005	FRD03-POD/S	16 & 24 Pin connectors at H/U	Radio must have "SAT" button & no factory DVD (RSE).
Explorer	2006-2009	FRD04-POD/S	16- Pin connector at headunit	Not compatible with factory Satellite, RSE or Navigation.
Five Hundred	2005-2006	Not Compatible		
F-150 Pick Up	1997	FRDF/PC-POD(2)	16- Pin connector at headunit	Must be CD Changer controlling radio.
F-Series Pick Up	1998-2003	FRDN/PC-POD(2)	20-Pin connector at headunit	Must be CD Changer controlling radio.
F-150	2006-2008	FRD04-POD/S	16- Pin connector at headunit	Not compatible with factory Satellite, RSE or Navigation.
F-250*	2006-2009	FRD04-POD/S	16- Pin connector at headunit	Not compatible with factory Satellite, RSE or Navigation.
F-350*	2006-2009	FRD04-POD/S	16- Pin connector at headunit	Not compatible with factory Satellite, RSE or Navigation.
*NOTE: Compatible with single CD radio models 6C3T-18C869AB and 6C3T-18C869-AD only.				
F-550	2006-2009	FRD04-POD/S	16- Pin connector at headunit	Not compatible with factory Satellite, RSE or Navigation.
Freestar	2004-2005	FRD03/PC-POD(2)	16 & 24 Pin connectors at H/U	Radio models 3F2T-18C868-AJ, 3F2T-18C869-AJ.
Focus	2000-2003	FRDC/PC-POD(2)	12-Pin connector at headunit	Must be CD Changer controlling radio. Not compatible with Blaupunkt headunit.
Focus	2006-2007	FRD04-POD/S	16-Pin connector at headunit	Not compatible with factory Satellite, RSE or Navigation.
Freestyle	2006-2007	FRD04-POD/S	16-Pin connector at headunit	Not compatible with factory Satellite, RSE or Navigation.
Fusion	2006-2009	FRD04-POD/S	16-Pin connector at headunit	Not compatible with factory Satellite, RSE or Navigation.
HN80 Heavy Duty	1996-1997	FRDF/PC-POD(2)	16-Pin connector at headunit	Must be CD Changer controlling radio.
Mustang	2001-2004	FRDN/PC-POD(2)	20-Pin connector at headunit	Must be CD Changer controlling radio.
Mustang	2004	FRD03/PC-POD(2)	16 & 24 Pin connectors at H/U	Must be CD Changer controlling radio.
Mustang	2004	FRD03-POD/S	16 & 24 Pin connectors at H/U	Radio must have "SAT" button.
Mustang	2006-2009	FRD04-POD/S	16-Pin connector at headunit	Not compatible with factory Satellite, RSE or Navigation.
Ranger	1995-1997	FRDF/PC-POD(2)	16-Pin connector at headunit	Must be CD Changer controlling radio.
Ranger	1998-2004	FRDN/PC-POD(2)	20-Pin connector at headunit	Must be CD Changer controlling radio.
Sport Trac	2000-2005	FRDN/PC-POD(2)	20-Pin connector at headunit	Must be CD Changer controlling radio.
Sport Trac	2004-2005	FRDN-POD/S	20-Pin connector at headunit	Radio must have "SAT" button.
Sport Trac	2004-2005	FRD03-POD/S	16 & 24 Pin connectors at H/U	Radio must have "SAT" button.
Sport Trac	2007-2009	FRD04-POD/S	16-Pin connector at headunit	Not compatible with factory Satellite, RSE or Navigation.
Taurus	1996-2006	FRDR/PC-POD(2)	RCU in rear driver side panel	Must be CD Changer controlling radio (oval/trapezoidal).
Thunderbird	2001-2003	FRDN/PC-POD(2)	20-Pin connector at headunit	Must be CD Changer controlling radio.
Thunderbird	2004-2005	FRD03-POD/S	16 & 24 Pin connectors at H/U	Radio must have "SAT" button.
Windstar	1999-2003	FRDN/PC-POD(2)	20-Pin connector at headunit	Must be CD Changer controlling radio.

Note 1: FRD03-POD/S and FRDN-POD/S – not compatible with Touch-screen Navigation. Also, takes place of factory satellite (if present).

Note 2: FRD04-POD/S not compatible with Navigation radio, or if equipped with factory Satellite, RSE (Rear Seat Entertainment), and Sync system.

NOTE: Vehicles that use the "POD(2)" series parts must have external CD Changer controls.

Vehicles that use the "POD/S" series parts must have Satellite controls.

GMC		PIE Part #	Without XM	With XM	
Canyon	2004-2008	GM12-POD/S	GM12-R1	GM12-X1	Must have ' BAND ' button.
Canyon	2004-2008	GM2L-POD/S	GM2L-R03	GM2L-X03	Must have ' BAND ' button.
Envoy	2004-2008	GM12-POD/S	GM12-R1	GM12-X1	Must have ' BAND ' button.
Envoy	2004-2008	GM2L-POD/S	GM2L-R03	GM2L-X03	Must have ' BAND ' button.
Sierra	2003-2006	GM12-POD/S	GM12-R1	GM12-X1	Must have ' BAND ' button.
Sierra	2003-2006	GM2L-POD/S	GM2L-R03	GM2L-X03	Must have ' BAND ' button.
Sierra Classic	2007	GM12-POD/S	GM12-R1	GM12-X1	Must have ' BAND ' button.
Sierra Classic	2007	GM2L-POD/S	GM2L-R03	GM2L-X03	Must have ' BAND ' button.



**iPod INTERFACE FOR OEM CD 'CHANGER READY' OR
'SATELLITE READY' HEADUNITS**

MAKE/MODEL	YEAR(S)	PIE PART#			LOCATION	NOTES
		PIE Part #	Without XM	With XM		
Sierra (New Body)	2007-2008	GMLAN-POD/S	GMLAN-R1	GMLAN-X1	Must have 'CAT' button.	
Sierra (New Body)	2007-2008	GM2L-POD/S	GM2L-R01	GM2L-X01	Must have 'CAT' button.	
Yukon/ XL/ Denali	2003-2006	GM12-POD/S	GM12-R1	GM12-X1	Must have 'BAND' button.	
Yukon/ XL/ Denali	2003-2006	GM2L-POD/S	GM2L-R03	GM2L-X03	Must have 'BAND' button.	
Yukon/ XL/ Denali	2007-2008	GMLAN-POD/S	GMLAN-R1	GMLAN-X1	Must have 'CAT' button.	
Yukon/ XL/ Denali	2007-2008	GM2L-POD/S	GM2L-R01	GM2L-X01	Must have 'CAT' button.	

Note: Must be XM capable radio.

HONDA

Accord	1992-1997	HON/PC-POD(2)	8-Pin connector at headunit	
Accord	1998-2002	HON98/PC-POD(2)	14-Pin connector at headunit	
Accord	2003-2008	HON03-POD/S	14-Pin connector at headunit	Must have 'XM' button.
Civic	1992-1998	HON/PC-POD(2)	8-Pin connector at headunit	
Civic	1999-2005	HON98/PC-POD(2)	14-Pin connector at headunit	Compatibility includes Si and Hybrid models.
Civic	2006-2008	HON03-POD/S	14-Pin connector at headunit	Must have 'XM' button.
CRV	1997-1998	HON/PC-POD(2)	8-Pin connector at headunit	
CRV	1999-2004	HON98/PC-POD(2)	14-Pin connector at headunit	
CRV	2005-2008	HON03-POD/S	14-Pin connector at headunit	Must have 'XM' button.
Del Sol	1993-1997	HON/PC-POD(2)	8-Pin connector at headunit	
Element	2003-2008	HON03-POD/S	14-Pin connector at headunit	Must have 'XM' button.
Odyssey	1995-1998	HON/PC-POD(2)	8-Pin connector at headunit	
Odyssey	1999-2004	HON98/PC-POD(2)	14-Pin connector at headunit	
Odyssey	2005-2008	HON03-POD/S	14-Pin connector at headunit	Must have 'XM' button.
Passport	1995-UP	Not Compatible		
Pilot	2003-2005	HON98/PC-POD(2)	14-Pin connector at headunit	
Pilot	2006-2008	HON03-POD/S	14-Pin connector at headunit	Must have 'XM' button.
Prelude	1992-1998	HON/PC-POD(2)	8-Pin connector at headunit	
Prelude	1999-2001	HON98/PC-POD(2)	14-Pin connector at headunit	
Ridgeline	2006-2008	HON03-POD/S	14-Pin connector at headunit	Must have 'XM' button.
S2000	2000-2003	HON98/PC-POD(2)	14-Pin connector at headunit	
S2000	2004-2008	HON03-POD/S	14-Pin connector at headunit	Must have 'XM' button.

Note 1: HON98/PC-POD(2) not compatible with 6-disc in-dash radios.

Note 2: Radios without shuffle or repeat function do not support BANK select feature on POD parts.

Note 3: HON03-POD/S not compatible with factory Navigation radios. Is compatible with factory XM installed.

HUMMER

		PIE Part #	Without XM	With XM	
H2	2003-2007	GM12-POD/S	GM12-R1	GM12-X1	Must have 'BAND' button.
H2	2003-2007	GM2L-POD/S	GM2L-R03	GM2L-X03	Must have 'BAND' button.
H3	2006-2008	GM12-POD/S	GM12-R1	GM12-X1	Must have 'BAND' button.
H3	2006-2008	GM2L-POD/S	GM2L-R03	GM2L-X03	Must have 'BAND' button.

Note: Must be XM capable radio.

ISUZU

		PIE Part #	Without XM	With XM	
Ascender 2WD	2005-2007	GM12-POD/S	GM12-R1	GM12-X1	Must have 'BAND' button.

Note: Must be XM capable radio.

JAGUAR



iPod INTERFACE FOR OEM CD 'CHANGER READY' OR 'SATELLITE READY' HEADUNITS

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION	NOTES
S Type	2000-2002	JAGW/PC-POD(2)	12-Pin Data cable in trunk	Not compatible with 2003 and Up S-Type.
S Type	2000-2002	JAG/PC-POD(2)	12-Pin Data port at headunit	Not compatible with 2003 and Up S-Type.

Note: Vehicles must have external CD Changer controls.

JEEP

All Models	1996-1998	CHRY/PC-POD(2)	8-Pin connector at headunit	Must be CD Changer controlling radio, "MODE" button.
Cherokee	1996-1998	CHRY/PC-POD(2)	8-Pin connector at headunit	Must be CD Changer controlling radio, "MODE" button.
Commander	2006-2007	CHRY04/PC-POD2	10 & 22-Pin connectors at headunit	Compatible with RAQ, RAK, REC radios only.
Compass	2007-2008	CHRY04/PC-POD2	10 & 22-Pin connectors at headunit	Compatible with RAQ, RAK, REC radios only.
Grand Cherokee	1996-1998	CHRY/PC-POD(2)	8-Pin connector at headunit	Must be CD Changer controlling radio, "MODE" button.
Grand Cherokee	1999-2001	CHRY98/PC-POD(2)	8-Pin connector at headunit	Must be CD Changer controlling radio, 'CD-C' button.
Grand Cherokee	2002-2004	CHRY02/PC-POD(2)	10-Pin connector at headunit	Must be CD Changer controlling radio, 'MODE' button.
Grand Cherokee	2005-2007	CHRY04/PC-POD2	10 & 22-Pin connectors at headunit	Compatible with RAQ, RAK, REC radios only.
Liberty	2002-2007	CHRY02/PC-POD(2)	10-Pin connector at headunit	Must be CD Changer controlling radio, 'MODE' button.
Patriot	2007-2008	CHRY04/PC-POD2	10 & 22-Pin connectors at headunit	Compatible with RAQ, RAK, REC radios only.
Wrangler	1997-1998	CHRY/PC-POD(2)	8-Pin connector at headunit	Must be CD Changer controlling radio, "MODE" button.
Wrangler	2002-2006	CHRY02/PC-POD(2)	10-Pin connector at headunit	Must be CD Changer controlling radio, 'MODE' button.

Note 1: Not compatible with "RBQ" (6-disc in-dash), "RB4" (Navigation), "RAH" and "REV" radios.

Note 2: CHRY04/PC-POD2 is not compatible with factory VES installed. Is compatible with factory satellite installed.

LEXUS

ES330	2005-2006	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
ES350	2007-2008	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
GS300	2006	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
GS350	2007	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
GS430	2006-2007	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
GS450h	2007-2008	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
GS460	2008	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
GX470	2007-2008	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
IS 250	2006-2008	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
IS 350	2006-2008	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
IS-F	2007-2008	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
LS430	2004-2006	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
LX470	2005-2007	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
RX350	2007-2008	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
RX400h	2006-2008	TOY03-POD/S	12-Pin connector	Must have "SAT" button.

Note: The TOY03-R1 radio harness is required with all of the above vehicles. The TOY03-POD/S will retain XM radio.

LINCOLN

2004 Models equipped with 6-Disc in-Dash, THX certified, Navigation radio, may use Part # FRD03/PC-POD(2).

Aviator	2002-2003	FRDN/PC-POD(2)	20-Pin connector at headunit	Must be CD Changer controlling radio.
Aviator	2004-2005	FRD03PC-POD(2)	16 & 24-Pin connectors at H/U	Must be CD Changer controlling radio.
Aviator	2004-2005	FRD03-POD/S	16 & 24 Pin connector at H/U	Radio must have "SAT" button & no factory DVD (RSE).
Continental	1995-1997	FRDF/PC-POD(2)	16-Pin connector at headunit	Premium Audio System.
Continental	1995-1997	FRDR/PC-POD(2)	RCU in rear driver side panel	JBL or LUX Audio System.
Continental	1998-2002	FRDN/PC-POD(2)	20-Pin connector at headunit	Must be CD Changer controlling radio.
LS	2000-2003	FRDN/PC-POD(2)	20-Pin connector at headunit	Must be CD Changer controlling radio.
LS	2004-2005	FRD03/PC-POD(2)	16 & 24-Pin connectors at H/U	Must be CD Changer controlling radio.



iPod INTERFACE FOR OEM CD 'CHANGER READY' OR 'SATELLITE READY' HEADUNITS

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION	NOTES
LS	2004-2005	FRD03-POD/S	16 & 24 Pin connector at H/U	Radio must have "SAT" button.
Mark LT	2006-2008	FRD04-POD/S	16-Pin connector at headunit	Not compatible with factory Satellite, RSE or Navigation.
Mark VIII	1995-1998	FRDF/PC-POD(2)	16-Pin connector at headunit	Must be CD Changer controlling radio.
MKX	2007-2009	FRD04-POD/S	16-Pin connector at headunit	Not compatible with factory Satellite, RSE or Navigation.
Navigator	1997-1998	FRDF/PC-POD(2)	16-Pin connector at headunit	Must be CD Changer controlling radio.
Navigator	1999-2002	FRDN/PC-POD(2)	20-Pin connector at headunit	Must be CD Changer controlling radio.
Navigator	2004-2006	FRD03-POD/S	16 & 24-Pin connectors at H/U	Radio must have "SAT" button & no factory DVD (RSE).
Navigator	2007-200	FRD04-POD/S	16-Pin connector at headunit	Not compatible with factory Satellite, RSE or Navigation.
Town Car	1995-1997	FRDF/PC-POD(2)	16-Pin connector at headunit	Premium Audio System.
Town Car	1995-1997	FRDR/PC-POD(2)	RCU in rear driver side panel	JBL or LUX Audio System.
Town Car	1998-2002	FRDW/PC-POD(2)	12-Pin data cable in trunk or rear	Use FRDN if not pre-wired.
Town Car	2003-2004	FRD03/PC-POD(2)	16 & 24-Pin connectors at H/U	Must be CD Changer controlling radio.
Town Car	2005-2006	FRD03-POD/S	16 & 24-Pin connectors at H/U	Radio must have "SAT" button.

Note 1: FRD03-POD/S and FRDN-POD/S – not compatible with Touch-screen Navigation. Also, takes place of factory satellite (if present).

Note 2: FRD04-POD/S not compatible with Navigation radio, or if equipped with factory Satellite, RSE (Rear Seat Entertainment), and Sync system.

Note: Vehicles that use the "POD(2)" series parts must have external CD Changer controls.

Vehicles that use the "POD/S" series parts must have Satellite controls.

MAZDA

B Series Truck	1995-1997	FRDF/PC-POD(2)	16-Pin connector at headunit	Must be CD Changer controlling radio.
B Series Truck	1998-2001	FRDN/PC-POD(2)	20-Pin connector at headunit	Must be CD Changer controlling radio.
Tribute	2001-2002	FRDN/PC-POD(2)	20-Pin connector at headunit	Must be CD Changer controlling radio.

Note: Vehicles must have external CD Changer controls.

MERCURY

2004 Models equipped with 6-Disc in-Dash, THX certified, Navigation radio, may use Part # FRD03/PC-POD(2)

Cougar	1999-2002	FRDC/PC-POD(2)	12-Pin connector at headunit	Must be CD Changer controlling radio.
Grand Marquis	1995-1997	FRDF/PC-POD(2)	16-Pin connector at headunit	Premium Audio System
Grand Marquis	1995-1997	FRDR/PC-POD(2)	RCU in rear driver side panel	JBL or LUX Audio System
Grand Marquis	1998-2002	FRDN/PC-POD(2)	20-Pin connector at headunit	Must be CD Changer controlling radio.
Grand Marquis	2003-2004	FRD03/PC-POD(2)	16 & 24-Pin connectors at H/U	Must be CD Changer controlling radio.
Grand Marquis	2005-2006	FRD03-POD/S	16 & 24-Pin connectors at H/U	Radio must have "SAT" button
Marauder	2003-2004	FRD03/PC-POD(2)	16 & 24-Pin connectors at H/U	Must be CD Changer controlling radio.
Mariner	2005-2006	FRDN-POD/S	20-Pin connector at headunit	Radio must have "SAT" button & no factory DVD (RSE)
Mariner	2005-2006	FRD03-POD/S	16 & 24-Pin connectors at H/U	Radio must have "SAT" button & no factory DVD (RSE).
Milan	2006-2009	FRD04-POD/S	16-Pin connector at headunit	Not compatible with factory Satellite, RSE or Navigation.
Mountaineer	1997	FRDR/PC-POD(2)	RCU in rear passenger panel	JBL or LUX Audio System.
Mountaineer	1997	FRDF/PC-POD(2)	16-Pin connector at headunit	Premium Audio System.
Mountaineer	1998-2004	FRDN/PC-POD(2)	20-Pin connector at headunit	Must be CD Changer controlling radio.
Mountaineer	2005	FRD03-POD/S	16 & 24-Pin connectors at H/U	Radio must have "SAT" button & no factory DVD (RSE).
Mountaineer	2006-2009	FRD04-POD/S	16-Pin connector at headunit	Not compatible with factory Satellite, RSE or Navigation.
Monterey	2005-2006	Not Compatible		
Sable	1996-2006	FRDR/PC-POD(2)	RCU in rear driver side panel	JBL or LUX Audio System.
Tracer	1997-2002	FRDW/PC-POD(2)	12-Pin data cable in trunk/rear	Use FRDF/PC-POD(2) at headunit if not pre-wired.
Villager	1997-1998	FRDF/PC-POD(2)	16-Pin connector at headunit	Must be CD Changer controlling radio.
Villager*	1999-2002	FRDN/PC-POD(2)	20-Pin connector at headunit	Must be CD Changer controlling radio.

*Note 1: If the 2001-2002 Villager is equipped with factory video system, use PIE Part # FRDW/PC-POD(2).

Note 2: FRD03-POD/S and FRDN-POD/S – not compatible with Touch-screen Navigation. Also, takes place of factory satellite (if present).



iPod INTERFACE FOR OEM CD 'CHANGER READY' OR 'SATELLITE READY' HEADUNITS

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION	NOTES
------------	---------	-----------	----------	-------

Note 3: FRD04-POD/S not compatible with Navigation radio, or if equipped with factory Satellite, RSE (Rear Seat Entertainment), and Sync system.

Note: Vehicles that use the "POD(2)" series parts must have external CD Changer controls.

Vehicles that use the "POD/S" series parts must have Satellite controls.

MITSUBISHI

Eclipse	2003-2007	MIT-POD	14 or 22-Pin connector	Radio must have auxiliary capabilities.
Endeavor	2003-2005	MIT-POD	14 or 22-Pin connector	Radio must have auxiliary capabilities.
Grandis	2003-2007	MIT-POD	14 or 22-Pin connector	Radio must have auxiliary capabilities.
Galant	2003-2007	MIT-POD	14 or 22-Pin connector	Radio must have auxiliary capabilities.
Lancer	2003-2007	MIT-POD	14 or 22-Pin connector	Radio must have auxiliary capabilities.
Lancer Evolution	2003-2007	MIT-POD	14 or 22-Pin connector	Radio must have auxiliary capabilities.
Outlander	2003-2007	MIT-POD	14 or 22-Pin connector	Radio must have auxiliary capabilities.
Spyder	2003-2007	MIT-POD	14 or 22-Pin connector	Radio must have auxiliary capabilities.
Triton	2003-2007	MIT-POD	14 or 22-Pin connector	Radio must have auxiliary capabilities.

Note 1: To determine if radio is auxiliary capable - Press and hold 'CD' button for 3-5 seconds until "AUX" is displayed.

Note 2: Not compatible if factory auxiliary input jack is present.

NISSAN

Quest	1997-1998	FRDF/PC-POD(2)	16-Pin connector at headunit	Must be CD Changer controlling headunit.
Quest	1999-2003	FRDN/PC-POD(2)	20-Pin connector at headunit	Must be CD Changer controlling headunit.
Quest	2004-Up	Not Compatible		

Note: If the 2001-2003 Quest is equipped with factory video system, use PIE Part # FRDW/PC-POD(2).

OLDSMOBILE

		PIE Part #	Without XM	With XM	
Alero	2003-2004	GM12-POD/S	GM12-R1	GM12-X1	Must have 'BAND' button.
Alero	2003-2004	GM2L-POD/S	GM2L-R03	GM2L-X03	Must have 'BAND' button.

Note: Must be XM capable radio.

PLYMOUTH

Acclaim	1995	CHRY/PC-POD(2)	8-Pin connector at headunit
Breeze	1996-2000	CHRY/PC-POD(2)	8-Pin connector at headunit
Grand Voyager	1995-2000	CHRY/PC-POD(2)	8-Pin connector at headunit
Neon	1995-2000	CHRY/PC-POD(2)	8-Pin connector at headunit
Prowler	1997-2000	CHRY/PC-POD(2)	8-Pin connector at headunit
Voyager	1995-2000	CHRY/PC-POD(2)	8-Pin connector at headunit

Note 1: Radio must be one of the following CD Changer controller headunits:

- 5-preset radio with 5-band EQ, "DISC ^" and "DISC v" on presets 1 and 5, and "MODE" button,
- 6-preset radio w/Bass and Treble slider controls, "DIRECT DISC SELECT 1-6", printed above radio presets & "MODE/EJECT" button.

Note 2: Not compatible if equipped with a factory external CD Changer.

PONTIAC

		PIE Part #	Without XM	With XM	
Aztec	2003-2006	GM12-POD/S	GM12-R1	GM12-X1	Must have 'BAND' button.
Aztec	2003-2006	GM2L-POD/S	GM2L-R03	GM2L-X03	Must have 'BAND' button.
Grand AM	2003-2005	GM12-POD/S	GM12-R1	GM12-X1	Must have 'BAND' button.
Grand AM	2003-2005	GM2L-POD/S	GM2L-R03	GM2L-X03	Must have 'BAND' button.
Grand Prix	2004-2007	Not Compatible			



**iPod INTERFACE FOR OEM CD 'CHANGER READY' OR
'SATELLITE READY' HEADUNITS**

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION		NOTES
G5	2007	GM2L-POD/S	GM2L-R02	GM2L-X02	Must have 'CAT' button.
G6	2006-2007	Not Compatible			
		PIE Part #	Without XM	With XM	
Montana	2004-2006	GM12-POD/S	Not Available	GM12-X1	Must have factory XM Satellite installed.
Montana	2004-2006	GM2L-POD/S	Not Available	GM2L-X03	Must have factory XM Satellite installed.
Pursuit	2005-2006	GM2L-POD/S	GM2L-R05	GM2L-X02	Must have 'P-TYPE' button.
Solstice	2006-2008	GM2L-POD/S	GM2L-R02	GM2L-X02	Must have 'CAT' button.
Sunfire	2003-2005	GM12-POD/S	GM12-R1	GM12-X1	Must have 'BAND' button.
Sunfire	2003-2005	GM2L-POD/S	GM2L-R03	GM2L-X03	Must have 'BAND' button.
Torrent	2006	GM2L-POD/S	GM2L-R04	GM2L-X03	Must have 'XM/AUX' button.
Torrent	2007	GMLAN-POD/S	GMLAN-R1	GMLAN-X1	Must have 'CAT' button.
Torrent	2007	GM2L-POD/S	GM2L-R01	GM2L-X01	Must have 'CAT' button.

Note: Must be XM capable radio.

SAAB					
		PIE Part #	Without XM	With XM	
9-7x	2005-2007	GM12-POD/S	GM12-R1	GM12-X1	Must have 'BAND' button.
9-7x	2005-2007	GM2L-POD/S	GM2L-R03	GM2L-X03	Must have 'BAND' button.

Note: Must be XM capable radio.

SATURN					
		PIE Part #	Without XM	With XM	
Aura	2007	GM2L-POD/S	GM2L-R02	GM2L-X02	Must have 'CAT' button.
ION	2006-2007	GM2L-POD/S	GM2L-R02	GM2L-X02	Must have 'CAT' button.
Outlook	2007	GMLAN-POD/S	GMLAN-R1	GMLAN-X1	Must have 'CAT' button.
Outlook	2007	GM2L-POD/S	GM2L-R01	GM2L-X01	Must have 'CAT' button.
Relay	2005-2007	GM12-POD/S	GM12-R1	GM12-X1	Must have 'BAND' button.
Relay	2005-2007	GM2L-POD/S	GM2L-R03	GM2L-X03	Must have 'BAND' button.
Sky	2007	GM2L-POD/S	GM2L-R02	GM2L-X02	Must have 'CAT' button.
VUE	2006-2007	GM2L-POD/S	GM2L-R02	GM2L-X02	Must have 'CAT' button.

Note: Must be XM capable radio.

SCION					
		PIE Part #	Without XM	With XM	
Xa	2003-2007	TOY03-POD/S	12-Pin connector		Must have "SAT" button.
Xb	2003-2008	TOY03-POD/S	12-Pin connector		Must have "SAT" button.
Xd	2008	TOY03-POD/S	12-Pin connector		Must have "SAT" button.
Tc	2004-2008	TOY03-POD/S	12-Pin connector		Must have "SAT" button.

Note: The TOY03-R1 radio harness is required with all of the above vehicles. The TOY03-POD/S will retain XM radio.

Not compatible with OEL display radio.

TOYOTA					
		PIE Part #	Without XM	With XM	
4Runner	2006-2008	TOY03-POD/S	12-Pin connector		Must have "SAT" button.
Avalon	2005-2008	TOY03-POD/S	12-Pin connector		Must have "SAT" button.
Camry	2005-2008	TOY03-POD/S	12-Pin connector		Must have "SAT" button.
Camry Hybrid	2007-2008	TOY03-POD/S	12-Pin connector		Must have "SAT" button.
Corolla	2007-2008	TOY03-POD/S	12-Pin connector		Must have "SAT" button – RDS radios only.
Corolla S	2007-2008	TOY03-POD/S	12-Pin connector		Must have "SAT" button.



**iPod INTERFACE FOR OEM CD 'CHANGER READY' OR
'SATELLITE READY' HEADUNITS**

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION	NOTES
Corolla LE	2007-2008	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
FJ Cruiser	2007-2008	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
Highlander	2006-2007	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
Highlander Hybrid	2007-2008	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
Land Cruiser	2005-2007	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
Matrix	2007-2008	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
Matrix XRS	2007-2008	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
Matrix XR	2007-2008	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
Prius	2006-2008	TOY03-POD/S	12-Pin connector	Must be Satellite-ready.
Rav 4	2006-2008	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
Sequoia	2006-2007	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
Sienna	2006-2008	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
Tacoma	2007-2008	TOY03-POD/S	12-Pin connector	Must have "SAT" button.
Tundra	2007-2008	TOY03-POD/S	12-Pin connector	Must have "SAT" button.

Note: The TOY03-R1 radio harness is required with all of the above vehicles. The TOY03-POD/S will retain XM radio.

VOLKSWAGEN

Beetle	1998-2007	VWR/PC-POD(2)	12-Pin data cable in trunk or center console	
Cabrio	1998-2002	VWR/PC-POD(2)	8-Pin connector at headunit	
Eurovan	199-2003	VWR/PC-POD(2)	12-Pin connector at headunit	
Golf	1998-2002	VWR/PC-POD(2)	12-Pin connector at headunit	
Golf	2003-2007	VW02/PC-POD(2)	12-Pin data cable in trunk or center console	Must be Double DIN Radio w/ AM/FM/CASS/CD.
GTI	1999-2002	VWR/PC-POD(2)	8-Pin connector at headunit	
Jetta	1998-2001	VWR/PC-POD(2)	12-Pin connector at headunit	
Jetta	2002-2007	VW02/PC-POD(2)	12-Pin connector at headunit	Must be Double DIN Radio w/ AM/FM/CASS/CD.
Passat	1998-2002	VWR/PC-POD(2)	8-Pin connector at headunit	
Passat	2003-2007	VW02/PC-POD(2)	12-Pin connector at headunit	Must be Double DIN Radio w/ AM/FM/CASS/CD.
Touareg	2004-2006	VW02/PC-POD(2)	12-Pin connector at headunit	Must be Double DIN Radio w/ AM/FM/CASS/CD.

Note: Not compatible with factory Navigation (Excluding Touareg).

Note: Not compatible with factory satellite radio or external CD changer installed.

COMPATIBLE IPOD MODELS INCLUDE THE FOLLOWING:

mini / G3 / G4

nano (2G, 3G, 4G) / color / video / classic (2G) / touch (2G) / iPhone (3G) (POD2 & POD/S)